

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY, SINGAPORE 508734

VEHICLE NO : GBK1412G
MAKE & MODEL : NISSAN NV350 PANEL VAN 5DR 2.5 5AT
CHASSIS NO : JN1MC2E26Z0031480

DATE:
CLAIM TYPE :
D.O.A:

10 May 2022
TP CLAIM
12 Aug 2021

TO : CHINA TAIPING

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	LH REAR FENDER		\$ 2,308.20	\$ <i>Ry</i> 2,308.20
2	0	0		\$ -	\$ -
3	0	0		\$ -	\$ -
				\$ 2,308.20	\$ 2,308.20

Railing 66

TOTAL PRICE \$ *798.60* 2,308.20
LESS 10% \$ *310.68* 230.82
SUB TOTAL PRICE \$ *310.68* 2,077.38

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	JJ EXPRESS STICKER		\$ 250.00	\$ <i>150</i> 250.00
2					\$ -

TOTAL S/NETT \$ 250.00 \$ 250.00

Labour Charges

1	To cut, weld and panel beat to replace and repair on damaged parts	\$ 1,200.00	<i>500</i>
2	To putty and spray paint on LH rear fender and affected areas	\$ 800.00	<i>400</i>
2	To apply tuff coat on repair areas	\$ 150.00	<i>30</i>
3			

TOTAL LABOUR \$ 2,150.00

Total Cost of Repairs

\$ 4,477.38

PARTS = 798.60
LESS 10% = 79.86
T. PARTS = 718.74
S/NETT = 150.00
LABOUR = 930.00
TOTAL = 1798.74
-20% = 359.75
TOTAL = 1438.99
L/S = 1450.00

(Total parts + Total S/Nett + Total Labour Cost)

Tanpin 92495749

'WP' 11/5/22 @ 1530

L/S Resing after repair

Tanpin @ Mahanow

4 days