

ASS. REC. BY: arl

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s: Hock Wah Motor
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$74K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMW17227 Yr Regn: 05 Nov 2020
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit 1.5 c.c. 1496
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 11534 T/Radio: Insured / Std / NI / NA
 Eng/No: GP 53416103
 C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim or

Tyre Size: F: 205/45R16
 R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 26-08-21
 Survey held at w/s upm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Above mention vehicle was convert to OD, you might closed case.
	submit preli report

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Other (\$)

S + RS. SI

Photos

Other:

Report Form:

Form 100 / 1000

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO : SXXX8039G
QUEK EE SENG
BLK 732 TAMPINES STREET 71
13-119
SINGAPORE 520732
TEL : FAX :
PH : 96623544
ATTN :

6 Days.
Impress repair
After repair photos.
Guo Qiang.
82880282
26/8/2021

ESTIMATE BILL

Number : EB00005759
Date : 20/08/2021
Case No : AD00011996
Vehicle No : SMW1722T
Chassis : GP53416103
Year of Mfr : 2018
Policy No : 5119576149
Model : HONDA FIT HYBRID
1.5 AUTO

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE / one	1.0	885.40	20	708.32
2	TAILGATE LOCK X NN	1.0	98.10	20	78.48
3	TAILGATE RUBBER / Tin	1.0	92.30	20	73.84
4	TAILGATE OUTER CHROME	1.0	166.50	20	133.20
5	TAILGATE INNER GARNISH TRIMBOARD ?	1.0	98.00	20	78.40
6	TAILGATE EMBLEM / one	1.0	24.70	20	19.76
7	TAILGATE LOGO - FIT	1.0	30.10	20	24.08
8	TAILGATE LOGO - HYBRID ?	1.0	75.00	20	60.00
9	TAILGATE ABSORBER RH X NN	1.0	113.60	20	90.88
10	TAILGATE ABSORBER LH X NN	1.0	113.60	20	90.88
11	TAILGATE WINDSCREEN MOULDING / one	1.0	138.00	20	110.40
12	TAILGATE LAMP RH ?	1.0		20	
13	REAR FENDER RH / one	1.0	608.10	20	486.48
14	REAR FENDER INNER TRIMBOARD RH ?	1.0	210.50	20	168.40
15	REAR FENDER INNER SHIELD RH / one	1.0	98.40	20	78.72
16	SPARE TYRE PANEL ?	1.0	905.40	20	724.32
17	SPARE TYRE TOP TRIMBOARD ?	1.0	229.10	20	183.28
18	TAILLAMP RH / one	1.0	422.00	20	337.60
19	TAILLAMP PANEL RH / one	1.0	95.50	20	76.40
20	TAILLAMP CLIP / one	4.0	4.20	20	13.44
21	REAR FLOOR SIDE PANEL RH ?	1.0	190.10	20	152.08
22	END PANEL ?	1.0	388.20	20	310.56
23	END PANEL TOP GARNISH ?	1.0	111.80	20	89.44
24	REAR BUMPER / one	1.0	826.40	20	661.12
25	REAR BUMPER RETAINER RH / one	1.0	16.00	20	12.80
26	REAR BUMPER RETAINER LH X NN	1.0	16.00	20	12.80
27	REAR BUMPER BRACKET RH ?	1.0	14.00	20	11.20
28	REAR BUMPER BRACKET LH X	1.0	14.00	20	11.20
29	REAR BUMPER CENTER LOWER GARNISH ?	1.0	50.60	20	40.48
30	REAR BUMPER REFLECTOR RH ?	1.0	48.60	20	38.88
31	REAR BUMPER REFLECTOR GARNISH RH / one	1.0	47.60	20	38.08
32	REAR BUMPER REINFORCEMENT ?	1.0		20	
33	REAR BUMPER QUARTER GLASS RH / one	1.0		20	
34	REAR WHEEL BEARING RH X NN	1.0	306.60	20	245.28

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

101 BEDOK INDUSTRIAL PARK E
 101 NORTH AVE 4,
 101 08/10/12 SINGAPORE 489977
 101 6441 5655 FAX : 6441 5355/6243 8121
 101 C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX8039G
 QUEK EE SENG
 BLK 732 TAMPINES STREET 71
 13-119
 SINGAPORE 520732
 TEL : FAX :
 PH : 96623544
 ATTN :

ESTIMATE BILL

Number : EB00005759
 Date : 20/08/2021
 Case No : AD00011996
 Vehicle No : SMW1722T
 Chassis : GP53416103
 Year of Mfr : 2018
 Policy No : 5119576149
 Model : HONDA FIT HYBRID
 1.5 AUTO

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
35	REAR AXLE X NN	1.0		20	
36	REAR CENTRAL LOCK SENSOR	1.0		20	
37	REAR WHEEL RIM RH X NN	1.0	895.10	20	716.08
List Price - Parts Sub Total					5,876.88
38	SPARE TYRE RUBBER CARPET	1.0			
39	WINDSCREEN SEALANT	2.0	24.00	0	48.00
40	REVERSE SENSOR	1.0	280.00	0	280.00
41	REAR TYRE RH X NN	1.0	380.00	0	380.00
42	REVERSE CAMERA X	1.0	580.00	0	580.00
43	REAR DOOR RH - REPAIR	1.0			
44	REAR CHASSIS RH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					1,288.00
Parts Total					7,164.88
45	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,200.00	0	1,200.00
46	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
47	ANTI-RUST COATING	1.0	150.00	0	150.00
48	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
49	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
50	WIRING	1.0	40.00	0	40.00
51	TO REMOVE & REFIT UNDERCARRIAGE	1.0	350.00	0	350.00
52	FOUR WHEEL ALIGNMENT	1.0	180.00	0	180.00
53	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	200.00	0	200.00
Labour 1 Sub Total					3,650.00
SINGAPORE DOLLARS : ELEVEN THOUSAND FIVE HUNDRED SEVENTY-ONE AND CENTS NINETY-TWO ONLY			Less Excess		0.00
			SUBTOTAL		10,814.88
			GST 7.00%		757.04
			TOTAL		11,571.92

Date of accident : 20/08/2021 08:30 AM. Place : BEDOK NORTH ROAD NEAR BLK708

E. & O. E.

- the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

CUSTOMER SIGNATURE

Acknowledged by Repairer

Signature:
 Date:

HOCK WAH MOTOR WORKSHOP PTE LTD

AUTHORISED SIGNATURE

* N = Item not subjected to GST

Issued by : Anyisia