

REG NO : 48992400W

Chassis : WBA1A12070J211952

TP AxA
✓Qcon

S/N.	Item Description	Amount (\$)
1	Front Bonnet <i>Dented.</i>	\$ 1,462.50
2	Front Bonnet Undercover Clip x 1 set	\$ 50.00
3	Front Bonnet Hinge x 2 pcs	\$ 245.70
4	Front Bonnet Absorber x 2 pcs	\$ 304.20
5	Front Bonnet Lock (RH) <i>NEU</i>	\$ 111.15
6	Front Bonnet Lock Support (RH) <i>NEU</i>	\$ 60.30
7	Front Fender (RH) <i>Distorted.</i>	\$ 760.50
8	Front Fender Inner Garnish (RH) <i>Deformed</i>	\$ 128.70
9	Front Fender Inner Garnish Clip x 1 set <i>NEU</i>	\$ 50.00
10	Headlamp (RH) <i>Smashed.</i>	\$ 2,223.00
11	Headlamp Bulb <i>Damaged.</i>	\$ 526.50
12	Headlamp Control Unit <i>3 NEU</i>	\$ 1,053.00
13	Headlamp Driver Module <i>NEU</i>	\$ 959.40
14	Headlamp Panel Bracket (RH) <i>Damd</i>	\$ 15.80
15	Headlamp Panel (RH) <i>Bent</i>	\$ 128.70
16	Headlamp Washer Motor (RH) <i>Cracked</i>	\$ 204.75
17	Headlamp Washer Cover (RH) <i>Damaged.</i>	\$ 56.16
18	Front Bumper <i>Distorted</i>	\$ 1,345.50
19	Front Bumper Clip x 1 set <i>NEU</i>	\$ 50.00
20	Front Bumper Side Retainer (RH) x 2 pcs <i>Damd.</i>	\$ 81.90
21	Front Bumper Sponge <i>Cracked.</i>	\$ 76.05
22	Front Bumper Reinforcement <i>Bent</i>	\$ 479.70
23	Front Bumper Undercover <i>NEU</i>	\$ 266.90
24	Front Bumper BMW Logo <i>NEU</i>	\$ 77.30
25	Foglamp (RH) <i>cracked</i>	\$ 374.40
26	Foglamp Cover (RH) <i>cracked.</i>	\$ 111.15
27	Front Chrome Grille (RH) <i>NEU</i>	\$ 116.90
28	Front Support Panel Top Rubber <i>NEU</i>	\$ 56.16
29	Front V-Brace <i>NEU</i>	\$ 119.60
30	Front Top Air Dust <i>3 torn</i>	\$ 234.00
31	Front Bottom Air Dust	\$ 265.80
32	Air Duct (RH) <i>NEU</i>	\$ 90.30
33	Front Door (RH) <i>Repair</i>	\$ 1,345.50



高領摩哆貿易公司 KAOLIN MOTOR PTE. LTD.

Oxley Bizhub. 71 Ubi Road 1, #05-35. S(408732)

Tel : +65 8800 9090 Email : kaolin2020hq@gmail.com

CASH SALE

Messrs

Cash

No. 281700290

Date 24/08/2024

Vehicle No.

SKK7580

Model

Destination

Kapi Bukit Ave 6 #01-54

Time In

Time Out

Amount \$

100

Remarks

- ☐ Change Spare Tyre / Jumpstart
- ☐ Basement / Multi Carpark
- ☐ Accident
- ☐ Using King Dolly (Extra Trailer)

- ☐ Loaded With Goods
- ☐ Dismantle Shaft / Brake / Equipment
- ☐ Open Door
- ☐ Crane up / Winch out

P28175

Driver

Received By

bisSAFE