

REG BY: Thuan

REG: China

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

NO GIA given

Date/Time File Pass to?

☐

: Prelim. Report

1)

☐

: Final Report

Date/Time File Return to?

2)

Report Form:

Every Sign / Initial

Veh No:

✓ SHA2993X

Yr Regn:

18/4, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / ✓ Prime Mover /

Truck / Trailer or

Make:

Hyundai Ioniq

c.c 1580

Colour:

blue

A/C: Insured / Std / NI / NA

Sp. Reading

223030

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

HMLC851CUN141877

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SIR / STD A/Rlm or

Tyre Size:

F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

24/8/21

D.O.A.

24/8/21 1600

Survey held at

Comfort

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Roof/lop or

The UIC / Chassis frame / Body Structure affected due to collision.

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Wash and

Survey Fee:

Transportation:

\$ + RS. \$

Fuel

Others

Total