

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21008968/VQF3N2**Date:** 07/09/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS010021
Claimant Vehicle No :	SHB2026H	Insured Vehicle No :	GBG5326S
Date of Loss:	24/08/2021	Nature of Claim:	TP Claim No: M2103921

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB2026H	Engine No:	D4FDEU463470
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMHU097796
Reg. Date:	22/12/2016 (Man. Year: 2016)	Odometer:	659490 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	206/60R16	Rear Tyre Size:	206/60R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,432.26	3,613.06	1,819.20	33.49
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,930.00	1,180.00	750.00	38.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,373.26	4,804.06	2,569.20	34.84
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	7,373.26	3,850.00	3,523.26	47.78
+ GST 7.00/7.00% (S\$)	516.13	269.50	246.63	47.78
Nett Amount (S\$)	7,889.39	4,119.50	3,769.89	47.78

INSPECTION

Date of Assignment:	25/08/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	25/08/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB2026H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOOTLID COVER	Deformed	2,609.80 FL	-	*2,609.80 FL
2	1		*BOOTLID HINGE LH	Serviceable	142.30 FL	-	*- FL
3	1		*BOOTLID HINGE RH	Serviceable	142.30 FL	-	*- FL
4	1		*BOOTLID EMBLEM - H	Necessary	63.10 FL	-	*63.10 FL
5	1		*BOOTLID EMBLEM - CRDI	Necessary	52.40 FL	-	*52.40 FL
6	1		*BOOTLID EMBLEM - I40	Necessary	67.90 FL	-	*67.90 FL
7	1		*REAR BUMPER ASSY	Cut	1,106.00 FL	-	*1,106.00 FL
8	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
9	1		*REAR BUMPER SPONGE	Serviceable	119.50 FL	-	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Serviceable	428.40 FL	-	*- FL
11	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Serviceable	180.80 FL	-	*- FL
12	1		*REAR BUMPER REINFORCEMENT BRACKET RH	Serviceable	180.80 FL	-	*- FL
13	1		*REAR BUMPER UNDER COVER	Cut	288.00 FL	-	*288.00 FL
14	1		*REAR END PANEL	Serviceable	526.70 FL	-	*- FL
15	1		*REAR END PANEL GARNISH	Serviceable	57.70 FL	-	*- FL
16	1		*REAR LOWER PANEL	Serviceable	495.50 FL	-	*- FL
17	1		*REAR BUMPER MAT	Necessary	50.00 F	-	*50.00 FS
18	1		*REVERSE SENSOR	Cut	135.70 F	-	*135.70 FS
19	1		*BOOTLID COMFORTDELGRO LOGO	Necessary	30.00 F	-	*30.00 FS
20	1		*BOOTLID COMFROT TEL.NO STICKER	Necessary	30.00 F	-	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,728.90	4,454.90
- List Item Discount on L Items 20.00/20.00% (\$)	1,296.64	841.84
Total Parts (\$)	5,432.26	3,613.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	560.00
2	SPRAYPAINT	New	800.00	500.00
3	CHECK WIRING	New	50.00	20.00
4	TUFF KOTE	New	50.00	20.00
5	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
6	ADVERTISEMENT LOGO - BUMPER	New	50.00	50.00
Gross Labour Cost (\$\$)			1,930.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >