

ASS. REC. BY:

REF: CS/

SMR/ 21008969/Kuf3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SMP 16S

at Workshop m/s

of

Insured:

SHC 4877A

Policy No.

Claims No.

TAX/08/21/2042

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Smp 16S

Yr Regn:

03/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey

c.c

2356

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

93822

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

THMRC 1890 G C 202227

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

20/8/21

D.O.I.

30/8/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ Simon said I.A.I. unable to locate 2nd parts

Confirmed final fig P/P \$4382.56, 5 repair days.

(RED \$2442.96; 36%)

Date/Time, File Pass to?

☐

Prell. Report

1) 20/9 TYPIST

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Fuel:

Others

TOTAL

Report Format:

TP

Lump Sum / I.B.I. (\$

\$4382.56

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 31969

Vehicle Insured : SHC 4877 A
Accident Date : 20-Aug-2021

Date : 25-Aug-2021

Our Ref : 021338 (FIRST CAP) / SANDRA

PAGE : 1

LIM JIT WAN (MR)
Singapore

Not Authorized
5 days Recovery After Repair

ESTIMATED COST OF REPAIR FOR HONDA ODYSSEY 2.4 EXV-S CVT (2016) SMP16S

1 pc rear bumper		R 606.10	✓
2 pcs rear bumper side retainer (LH/RH)	@ S\$ 22.30	sn 44.60	X
14 pcs rear bumper clips	@ S\$ 4.90	sn 68.60	✓
1 pc n/s rear bumper reflector		sn 43.80	X
2 pcs rear bumper lower spoiler (LH/RH)	@ S\$124.70	sn 249.40	X
1 pc rear bumper parking sensor (1 set)		400.30	?
1 pc n/s rear bumper side garnish		sn 85.30	X
1 pc tailgate		R 1,171.20	✓
1 pc tailgate lock		sn 203.60	✓
1 pc tailgate weatherstrip		sn 120.90	✓
1 pc tailgate lower chrome		195.30	?
1 pc tailgate glass moulding		sn 95.00	✓
1 pc tailgate inner trimboard		282.20	?
1 pc tailgate inner pocket handle		sn 21.50	X
1 pc tailgate buzzer		75.50	?
1 pc tailgate keyless antenna		85.10	?
1 pc rear end panel		491.40	?
1 pc rear end panel top garnish		sn 110.50	✓
1 pc n/s rear fender inner trimboard		925.30	?
1 pc spare tyre panel		R 431.30	X
		5,706.90	
	Less 20% :	-1,141.38	
		4,565.52	
1 pc tailgate glass sealant		sn 40.00	sn ✓

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SHC 4877 A
Our Ref : 021338

Page : 2
No. : 31969

1 pc tailgate glass damping seal	20.00 sn ✓
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	800.00 7
To apply undersealing	120.00 601
To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works	180.00 801
To remove and renew rear windscreen glass and conduct water leak test.	120.00 ✓
To transfer tailgate's fittings	80.00 601
To putty and respray on affected portions.	900.00 6601
Total :	S\$ 6,825.52

Singapore Dollars SIX THOUSAND EIGHT HUNDRED
TWENTY FIVE AND CENTS FIFTY TWO Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claims on a "Without Prejudice" basis
- No illegal deduction(s) is allowed
- Supplementary claims must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 20/08/2021 10:05 (SGT)
Date of Accident 20/08/2021 06:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information ALONG MARYMOUNT ROAD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMP16S

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner LIM JIT WAN (LIN RIHUAN)
NRIC No S7236449Z
Email Address MOLBY_LIM@YAHOO.COM
Mobile Phone No (Phone) +65-96938233
Alternative Phone No +65-96938233

VEHICLE PARTICULARS

Manufacturer Honda
Model Odyssey
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 2400

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5077872733-05
Cover Note Number -

DRIVER

Name of Driver LIM JIT WAN (LIN RIHUAN)
NRIC No S7236449Z

A
B

A - SMP 1163

B - SHC 4877A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I brake due to the vehicle in front. Vehicle B

could not stop in time and hit into my vehicle.

My front rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 24/07/2021

10:00hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: HENRY

NRIC/ID No.: 5192277