



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STAR AUTO PERFORMANCE PTE LTD 176 SIN MING DRIVE #04-05 SIN MING AUTOCARE SINGAPORE 575721			Ref: CS/TP21008975/Kvce2	
			Date: 31/08/2021	
			Code: TP535	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	WBA7T22040BM60990	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	25/08/2021	
2. Vehicle Particulars & Condition				
	Make & Model	BMW 740LI (A)	c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	WBA7T22040BM60990	Colour	METALLIC DARK BLUE
	Odometer	6908 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/40 R20	PIRELLI	9 mm
	L/H Front Tyre	245/40 R20	PIRELLI	9 mm
	R/H Rear Tyre	275/35 R20	PIRELLI	9 mm
	L/H Rear Tyre	275/35 R20	PIRELLI	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	Inspection Date	25/08/2021	
	Survey held at	STAR AUTO PERFORMANCE PTE LTD 176 SIN MING DRIVE, #04-05, SIN MING AUTOCARE, SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			