

Date: 25.08.2021

Vehicle No: SMQ9890U

Model: HONDA VEZEL HYBRID 1.5Z

Chassis: RU31208880-2016

Reg. Year: 2019

Third Party Insurer:

Third Party Veh No:

Date of Accident:

Estimator:

Surveyor:

AIG

SMR5531C

25.08.2021

TING AN

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE <i>953</i>	1		<i>RM</i> \$972.40
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>RM</i> \$65.60
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>RM</i> \$75.60
4	REAR TAILGATE INNER TRIM BOARD	1		<i>RM</i> \$203.50
5	REAR TAILGATE INNER LOCK	1		<i>R</i> \$116.40
6	REAR TAILGATE WEATHERSTRIPE	1	<i>DIY / RM</i>	\$138.60
7	REAR WINDSCREEN MOULDING	1	<i>RM</i>	\$105.20
8	REAR TAILGATE GARNISH COVER	1	<i>RM</i>	\$206.50
9	REAR TAILGATE LAMP RH	1	<i>CM</i>	\$432.40
10	REAR TAIL LAMP RH <i>434.60</i>	1	<i>RM</i>	\$486.70
11	REAR BUMPER <i>762.70</i>	1	<i>RM</i>	\$829.60
12	REAR BUMPER SIDE BRACKET RH	1	<i>DIY</i>	\$37.50
13	REAR BUMPER REFLECTOR RH	1	<i>CM</i>	\$108.50
14	REAR SIDE BUMPER RH	1	<i>RM</i>	\$148.50
15	REAR END PANEL	1	<i>RM</i>	\$452.40
16	REAR END PANEL UPPER COVER	1	<i>DIY</i>	\$103.60
17	REAR FLOOR PANEL	1	<i>R</i>	\$939.20
18	REAR FLOOR SIDE PANEL RH	1	<i>R</i>	\$156.50
19	REAR SPARE TYRE TRAY	1	<i>CM</i>	\$236.10
20	REAR SPARE TYRE TRAY UPPER BOARD <i>381</i>	1	<i>DIY</i>	\$459.90
21	REAR EXHAUST	1	<i>RM</i>	\$602.50
22	REAR EXHAUST HEAT SHIELD	1	<i>RM</i>	\$40.10
23	HYBRID BATTERY CASE COVER	1	<i>RM</i>	\$346.60
24	REAR FENDER RH <i>991.00</i>	1	<i>RM</i>	\$1,063.60
25	REAR FENDER WHEEL ARCH COVER RH	1	<i>RM</i>	\$193.10
26	REAR FENDER INNER SHIELD RH	1	<i>RM</i>	\$130.30
27	REAR FENDER INNER TRIM BOARD RH	1	<i>RM</i>	\$290.80
28	REAR FENDER INNER TOP GARNISH COVER RH	1	<i>RM</i>	\$95.40
29	REAR FENDER INNER PANEL RH	1	<i>R</i>	\$701.10
30	REAR ABSORBER RH	1	<i>RM</i>	\$271.20
31	REAR WHEEL BEARING ASSY RH <i>139</i>	1	<i>RM</i>	\$341.60
32	REAR AXLE BEAM <i>1490.70</i>	1	<i>RM</i>	\$1,689.90
33	REAR DOOR RH	1		REPAIR
SUB TOTAL				\$12,040.90
LESS 20%				-\$2,408.18
PARTS TOTAL				\$9,632.72

Head office

8 Rong Chong Road Singapore 159143
Tel: (65) 8472 1213 | Fax: (65) 8472 212

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (65) 6484 9910 | Fax: (65) 6481 1993

Branch (Motor Insurance Claims)

8A 10 Ang Mo Kio 2nd Park 2A #01-05 Singapore 568047
Tel: (65) 6481 1522 | Fax: (65) 6481 1011



Date: 25.08.2021
Vehicle No: SMQ9890U
Model: HONDA VEZEL HYBRID 1.5Z
Chassis: RU31208880-2016
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SMR5531C
Date of Accident: 25.08.2021
Estimator: TING AN
Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE REAR EXHAUST & ETC. \$180.00 601
TO DIAGNOSIS FAULT CODE & RESET MEMORY. \$150.00 X
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$100.00 201

LABOUR TOTAL \$4,530.00

TING AN TOTAL \$14,912.72

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

81K 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 25.08.2021
Vehicle No: SMQ9890U
Model: HONDA VEZEL HYBRID 1.5Z
Chassis: RU31208880-2016
Reg.Year: 2019

Third Party Insurer: AIG
Third Party Veh No: SMR5531C
Date of Accident: 25.08.2021
Estimator: TING AN
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE INNER TRIM BOARD CLIPS	1		Ne \$40.00 ✓
2	REAR WINDSCREEN SEALANT	1		Ne \$80.00 405m
3	REAR BUMPER CLIPS	1		Ne \$50.00 ✓
4	REAR BUMPER REVERSE SENSOR	1		Shon \$300.00 200m
5	REAR END PANEL UPPER COVER CLIPS	1		Ne \$30.00 ✓
6	REAR END PANEL JOINT SEALANT	1		Ne \$80.00 50m
7	REAR FENDER INNER TRIM BOARD CLIPS RH	1		Ne \$80.00 ✓
8	REAR FENDER INNER SHIELD CLIPS RH	1		Nn \$40.00 X
9	REAR NUMBER PLATE & HOLDER	1		Sh \$50.00 X
S/N TOTAL				\$750.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$1,600.00 1200/

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR SIDE BUMPER RH, REAR END PANEL, REAR FLOOR PANEL, REAR FENDER RH, REAR DOOR RH & ETC.

\$1,600.00 1100/

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT, REAR WINDSCREEN MOULDING & ETC. TO EFFECT REPLACE OF REAR TAILGATE.

\$150.00 120/

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

\$120.00 60/

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00 50/

LABOUR CHARGES TO REMOVE & REPLACE REAR ABSORBER, REAR WHEEL BEARING ASSY RH, REAR AXLE BEAM & ETC.

\$300.00 200/

TO WHEEL ALIGNMENT & BALANCING.

\$80.00 60/

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM RH, ROOF LINING & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

\$150.00 100/

Head office

8 Kung Ching Road Singapore 189643
Tel: (65) 6472 1113 | Fax: (65) 6472 9119

Branch

8A Serangoon North Ave 6 Singapore 554800
Tel: (65) 6484 9918 | Fax: (65) 6481 1993

Branch (Motor Insurance Claims)

100, 10 Ang Mo Kio St, Park RA 901-05 Singapore 568047
Tel: (65) 6401 1828 | Fax: (65) 6401 1011

