

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008982/UUCN2**Date:** 28/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00076832001

Claimant Vehicle No : FBH6465L **Insured Vehicle No :** GBH6942B

Date of Loss: 20/08/2021 Nature of Claim: TP Claim No: SNM21D204642/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBH6465L**

Make & Model: YAMAHA YBR125, 123cc (M) Engine No: E3J2E009436

Reg. Date: 13/08/2013 (Man. Year: 2013) Chassis No: LBPKE1783D0010396

Colour: Red/Black Odometer: 46015 km

Engine Capacity: 124 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 2.75-18 Rear Tyre Size: 3.00-18

Front Left Side: Michelin 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,403.50	2,833.90	2,569.60	47.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	495.00	335.00	160.00	32.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,898.50	3,168.90	2,729.60	46.28
Approved Total (Overridden) (\$\$)		2,000.00		
Nett Amount (\$\$)	5,898.50	2,000.00	3,898.50	66.09

INSPECTION

Date of Assignment: 26/08/2021

Date Inspected: 30/08/2021 Inspected At: Erofia Automotive Pte Ltd (HQ)
No 1, Kaki Bukit Avenue 6, #02-11
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Sep 2021)	
Parts:	N/A	YAMAHA YBR125 123cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH6465L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked	65.00 FL	*65.00 FL
2	1		*TOP COWLING	Cracked	105.00 FL	*105.00 FL
3	1		*WINDSHIELD	Cracked	55.00 FL	*55.00 FL
4	1		*HEADLAMP	Cracked	105.00 FL	*105.00 FL
5	1		*LAMPSTAY	Bent	180.00 FL	*60.00 FL
6	2		*FORK INNER TUBES	Bent	270.00 FL	*270.00 FL
7	2		*FORK OUTER TUBES	Bent	290.00 FL	*290.00 FL
8	1		*FORK UNDER BRACKET	Bent	145.00 FL	*145.00 FL
9	1		*FRONT BRAKE DISC	Bent	155.00 FL	*110.00 FL
10	1		*FRONT RIM SHAFT	Serviceable	45.00 FL	*- FL
11	1		*FRONT RIM BEARING	Damaged	52.00 FL	*30.00 FL
12	1		*FRONT SPORT RIM	Bent/Warped	320.00 FL	*320.00 FL
13	2		*FRONT SIGNALS	Scratched/Cracked	116.00 FL	*80.00 FL
14	1		*HANDLE-BAR	Bent	95.00 FL	*95.00 FL
15	1		*SET HANDLE-BAR GRIP	Torn	32.00 FL	*20.00 FL
16	1		*BRAKE LEVER	Cracked	50.00 FL	*30.00 FL
17	1		*CLUTCH LEVER (CUT)	Not Consistent With The Impact	50.00 FL	*- FL
18	2		*SIDE MIRRORS	N/s Grazed/O/s Broken	100.00 FL	*100.00 FL
19	1		*METER ASSY	Cracked	580.00 FL	*400.00 FL
20	1		*SIDE COWLINGS	N/s Cracked/O/s Repair	310.00 FL	*105.00 FL
21	1		*FUEL TANK	Repair	585.00 FL	*- FL
22	1		*SET FRONT FOOTREST	Bent	108.00 FL	*108.00 FL
23	1		*FRONT FOOTREST BRACKET	Bent	160.00 FL	*120.00 FL
24	1		*FRONT FOOTREST RUBBER	Torn	56.00 FL	*56.00 FL
25	1		*BRAKE PEDAL	Repair	48.00 FL	*- FL
26	1		*SIDE BOARD	Repair	45.00 FL	*- FL
27	1		*SET REAR FOOTREST	Serviceable	76.00 FL	*- FL
28	1		*REAR FOOTREST BRACKET	Serviceable	160.00 FL	*- FL
29	1		*EXHAUST PIPE	Repair	585.00 FL	*- FL
30	1		*EXHAUST PROTECTOR	Bent	42.00 FL	*42.00 FL
31	1		*SET REAR SIGNAL	Serviceable	150.00 FL	*- FL
32	1		*SET NUMBER PLATE	Frt Necessary	38.00 FS	*10.00 FS
33	2		*FORK OILS	Necessary	30.00 FS	*30.00 FS
34	2		*FORK OIL SEALS	Necessary	56.00 FS	*56.00 FS
35	1		*SET STEERING CONE BEARING	Necessary	98.00 FS	*98.00 FS
36	1		*REAR BOX	Cut	380.00 FS	*200.00 FS
37	1		*REAR BOX BRACKET	Repair	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,917.00	3,105.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	513.50	271.10
Total Parts (\$\$)	5,403.50	2,833.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD)	New	35.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	300.00
Gross Labour Cost (\$)			495.00	335.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >