$51\,UBI\,AVE\,1,\#01-25\,PAYA\,UBI\,INDUSTRIAL\,PARK,SINGAPORE\,408933\,TEL:(065)\,62563561\,FAX:(065)\,62564315$

Immediate Advice

To: AXA Insurance Pte Ltd DATE: 9/9/21

Survey details

Date of loss	23/8/21
Date of appointment	26/8/21
Date of survey	2/9/21
Location of survey	EQUATOR BROTHERHOOD

Vehicle Details:

THIRD PARTY
FBS 8138K
YAMAHA AEROX 155 CONNECTED ABS
14/7/2017
\$15,000.00
\$7,689.00
\$7,311.00

Repair details

Initial Estimate

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	
Number of days of repair	3 days (est)

Remarks:

Daamges Consistent

The estimated repair cost of the damaged vehicle is in the region of \$1,500.00-\$2,000.00