



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: ANG YVONNE			Ref: CS3/ASM21008985/Vvce2 Date: 10/09/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 1715D	Veh. Inspected	FBS 8138K
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03GGO	Excess (\$)	0.00
	Assign From	ANG YVONNE	Assign Date	26/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA AEROX	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MH3SG6420MJ007479	Colour	BLACK
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/80-14	PIRELLI	8 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	110/80-14	PIRELLI	8 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.			
5. General Information				
	Accident Date	23/08/2021	Inspect Date / Time	02/09/2021 (10:30 AM)
	Survey held at	EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

Report Ref No. CS3/ASM21008985/Vvce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.