

9136/Kp

ASS. F
HWA SENG SPRAY PAINTING PTE LD
160 Sin Ming Drive
#05-11 Sin Ming Autocity
SINGAPORE 575722
(COMPANY REGISTRATION NO.: 202017045G)
TEL : 64533100
FAX : 62669932

Date of Accident : 05/08/2021
Your Insured
Vehicle NO. EP 9800E

ESTIMATE REPAIR COSTS TO BMW 428i REG. NO. SBW 8383 Y

			SS	
1pc	Front Bumper		Bu 1450.00	✓
2pcs	Front Bumper Grille	e 128.60	CM 720.00	✓
1pc	Front Bumper Sponge		CM 62.10	✓
1pc	Front Bumper Reinforcement		R 418.60	✓
1pc	Front Number Plate Garnish		Sm 115.00	X
2pcs	Headlamp	o/s CM (\$2130.35/pc)	msm/cm 4260.70	✓
1pc	O/S LED Module		red/shm 427.25	✓
1pc	O/S Ballast		Sm 872.20	X
1pc	O/S Driver Module		Sm 767.55	✓
1pc	O/S Hid Bulb		Sm 424.95	✓
1pc	O/S Signal Bulb		Sm 59.05	✓
1pc	O/S Signal Bulb Socket		Sm 25.20	✓

9602.60
Less : 10% 960.26

8642.34

LABOUR & MISC CHARGES

Panel Knocking	550.00	2501
Spray Painting (Special Colour)	550.00	2501
Wire Checking	80.00	201
Labour to do Headlamp Reset	160.00	1001
Front Number Plate with Casing	Sm 60.00	X

TOTAL 10042.34

HWA SENG SPRAY PAINTING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Not Withheld
at Price @ 5100/pc
Meaning After Paint
3 days