

HWA SENG SPRAY PAINTING PTE LD
160 Sin Ming Drive
#05-11 Sin Ming Autocity
SINGAPORE 575722
(COMPANY REGISTRATION NO.: 202017045G)
TEL : 64533100
FAX : 62669932

Date of Accident : 05/08/2021
Your Insured
Vehicle No: EP 9800E

ESTIMATE REPAIR COSTS TO BMW 428i REG. NO. SBW 8383 Y

			S\$	
1pc	Front Bumper		Ben 1450.00	✓
2pcs	Front Bumper Grille	(\$360/pc)	720.00	?
1pc	Front Bumper Sponge		62.10	?
1pc	Front Bumper Reinforcement		418.60	?
1pc	Front Number Plate Garnish		115.00	X
2pcs	Headlamp	0/1 ? (\$2130.35/pc)	4260.70	?
1pc	O/S LED Module		427.25	?
1pc	O/S Ballast		872.20	X
1pc	O/S Driver Module		767.55	?
1pc	O/S Hid Bulb		424.95	?
1pc	O/S Signal Bulb		59.05	?
1pc	O/S Signal Bulb Socket		25.20	?

9602.60

Less : 10%

960.26

8642.34

LABOUR & MISC CHARGES

Panel Knocking	550.00	2501
Spray Painting (Special Colour)	550.00	2501
Wire Checking	80.00	201
Labour to do Headlamp Reset	160.00	?
Front Number Plate with Casing	60.00	X

TOTAL

10042.34

HWA SENG SPRAY PAINTING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Withheld
LKK &
Hwa Seng Spray Painting
3 days