



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR21006755/Vuf3e2-1	
			Date: 06/09/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 1415R	Veh. Inspected	SJC 1662Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/06/21/1028/KC	Excess (\$)	0.00	
Assign From	KAREN CHAN	Assign Date	26/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS AUTO	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JTDKB20U307726265	Colour	BLUE	
Odometer	511491 KM	Steering	IN ORDER	
Brakes	JAMMED	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	NEXEN	5 mm	
L/H Front Tyre	195/60 R16	NEXEN	5 mm	
R/H Rear Tyre	195/60 R16	NEXEN	5 mm	
L/H Rear Tyre	195/60 R16	NEXEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/06/2021	Inspection Date	16/06/2021	
Survey held at	KIM SENG TECK MOTOR WORKS BLK 3021A UBI ROAD 1 #01-42 SINGAPORE 408715			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	