

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 30 Aug 2021

Preliminary Advice

Vehicle No	: SJY6821H	Accident Date	: 21/08/2021
Make	: BMW 325I	Policy No.	: DMPCSNW00045322105
Assignment Date	: 30/08/2021	Excess	: S\$600.00
Date of Inspection	: 27/08/2021	Est. Duration of Repair	: 12
Inspection At	: HWA PENG AUTO SERVICE (1996) (HQ) 70 WOODLANDS INDUSTRIAL PARK E9 SINGAPORE 757836		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,167.25
Revised Amount	:S\$	16,932.66
Check Items (Estimated)	:S\$	10,066.45
Total	:S\$	26,999.11
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	29,640.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,360.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check items) stated are subject to part prices and labour cost.