

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

20-Aug-21

Our ref : TP/5017/21

Fong Wei Chiat Jensen

TP 111
Asher.

Indica

WBAXG12050DX48486

RE : estimate cost for vehicle no : SNA 5033B

1 pc	bootlid <i>Dented</i>	\$	2,276.00 ✓
1 pc	bootlid lock <i>and</i>		326.00 ✓
1 pc	bootlid w/strip <i>at</i>		245.00 ✓
2 pcs	bootlid reflectors <i>RH at</i>		736.00 368.
1 pc	bootlid logo <i>new</i>		90.00 ✓
1 pc	bootlid lock switch <i>new</i>		170.00 x
1 pc	bootlid trimboard <i>new</i>		564.00 x
10 pcs	bootlid trimboard clips <i>new</i>		50.00 x
2 pcs	bootlid hinges <i>new</i>		170.00 x
2 pcs	rear no plate lamp <i>new</i>		190.00 x
2 pcs	taillamp <i>LH at, RH cracked</i>		1,228.00 ✓
2 pcs	taillamp garnish <i>at</i>		<u>352.00</u> 70.
2 pcs	rear bumper reflector <i>new</i>		200.00 +
4 pcs	rear bumper reverse sensor <i>2 pieces dented</i>		992.00 496.
2 pcs	rear bumper retainer <i>new</i>		160.00 ✓
1 pc	rear bumper centre holder <i>amLd</i>		180.00 ✓
1 pc	rear bumper reinforcement <i>Best</i>		<u>896.00</u> 755
1 pc	rear bumper reinforcement lower garnish <i>cracked</i>		197.00 ✓
1 pc	rear bumper lower garnish <i>cracked</i>		262.00 ✓
1 pc	bootlid lock sensor wire <i>2 pieces dented</i>		220.00 ✓
1 pc	bootlid lock sensor ECU <i>new</i>		880.00 +
1 pc	end panel <i>dented</i>	9889	1,236.00 ✓ 964
1 pc	end panel inner garnish <i>amLd</i>	8900.10	376.00 ✓
1 pc	exhaust pipe <i>new</i>		1,263.00 1 DM
1 pc	spare tyre cardboard <i>dented</i>		562.00 351
1 pc	rear bumper tow hook cover <i>Missing</i>		62.00 ✓
			13,883.00
			less 10%
			1,388.30
			12,494.70
1 pc	rear bumper <i>Distorted</i>		3,000.00 snett 2000(SN)
1 pc	rear bumper diffuser <i>Distorted</i>		1,500.00 1200(SN)
1 pc	rear bumper sticker <i>new</i>	3630	200.00 80
1 pc	rear no plate <i>new</i>		40.00 x
2 pcs	exhaust pipe chrome <i>Best</i>		500.00 350.
			17,734.70

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

RE : estimate cost for vehicle no : SNA 5033B

Bal brought forward :----- \$ 17,734.70

Panel beating.	1,400.00	1000
Spray painting.	1,400.00	1000
Wiring.	30.00	✓
rust proofing.	80.00	✓
Remove & refit exhaust pipe.	80.00	x
	20,724.70	
Plus 7% GST	1,450.73	
	22,175.43	

SD : Twenty-two thousand one hundred seventy-five & cents forty-three only.

Adrian Ly

L/S 21/08/21.

07 days

total 14640.10

L/S: 11.7K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11.7K