

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SMY 9607 E**
 Model : Mercedes GLA200
 Year : 2021
 Chassis No : W1N2477872J170365

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

2021

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 3,186.30	\$ 2986.39 3,186.30
2	Tailgate logo	1	\$ 110.00	\$ 92.00 110.00
3	Tailgate emblem 'GLA200'	1	\$ 198.00	\$ 135.00 198.00
4	Tailgate inner lock	1	\$ 482.30	\$ 294.95 482.30
5	Tailgate inner lock stricker	1	\$ 110.00	\$ 110.00
6	Tailgate weatherstrip	1	\$ 498.00	\$ 498.00
7	Tailgate lamp	2	\$ 789.60	\$ 1440.00 1,579.20
8	Tailgate inner trim board	1	\$ 746.20	\$ 746.20
9	Tailgate reverse camera	1	\$ 620.00	\$ 620.00
10	Tailgate windscreen moulding	1	\$ 314.55	\$ 314.55
11	Rear bumper	1	\$ 1,858.00	\$ 1350.00 1,858.00
12	Rear bumper lower	1	\$ 983.35	\$ 775.00 983.35
13	Rear bumper chrome difusser	1	\$ 879.20	\$ 879.20
14	Rear bumper outer chrome garnish	1	\$ 441.60	\$ 441.60
15	Rear bumper side retainer	2	\$ 150.00 285.60	\$ 300.00 571.20
16	Rear bumper inner sponge	1	\$ 325.60	\$ 325.60
17	Rear bumper reinforcement	1	\$ 851.33	\$ 795.00 851.33
18	Rear bumper reinforcement bracket	2	\$ 152.00	\$ 304.00
19	Rear bumper bracket	2	\$ 145.82	\$ 291.64
20	Rear bumper reflector	2	\$ 65.00 198.00	\$ 130.00 396.00
21	Rear bumper centre beam	1	\$ 383.00	\$ 230.00 383.00
22	Rear bumper lower centre cover	1	\$ 428.79	\$ 428.79
23	Rear bumper reverse sensor	2	\$ 245.80	\$ 491.60 983.20
24	Rear end panel	1	\$ 2,136.60	\$ 2,136.60
25	Rear end panel top garnish	1	\$ 425.75	\$ 425.75
26	Taillamp	2	\$ 1,098.00	\$ 2,196.00
27	Taillamp lower bracket	2	\$ 198.00	\$ 396.00
28	Rear exhaust pipe	1	\$ 3,600.00	\$ 3,600.00
29	Rear exhaust pipe heatshield	2	\$ 336.00	\$ 672.00
30	Rear exhaust pipe cover	1	\$ 358.00	\$ 358.00

Parts Sub Total : \$ 26,325.81

10%

Discount : \$ 2,632.58

PARTS TOTAL : \$ 23,693.23

11,972.09

@ 10%

1197.21

10774.88

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Tailgate sealant	1	\$ 100.00	\$ 40.00	NECV
3	Tailgate windscreen sealant	1	\$ 100.00	\$ 40.00	NECV
4	Tailgate windscreen inner seal	1	\$ 80.00	\$ 30.00	NECV
5	Tailgate windscreen primer & cleaner	1	\$ 60.00	\$ 60.00	NNX
6	Tailgate inner trim board clips	1	\$ 60.00	\$ 30.00	NECV
7	Rear bumper clips	1	\$ 60.00	\$ 30.00	NECV
8	Rear bumper lower clips	1	\$ 60.00	\$ 60.00	NNX
9	Rear bumper chrome difusser clips	1	\$ 60.00	\$ 60.00	NNX
10	Rear bumper outer chrome garnish clips	1	\$ 60.00	\$ 60.00	NNX
11	Rear bumper reverse sensor seal	1	\$ 48.00	\$ 48.00	NNX
12	Rear end panel sealant	1	\$ 100.00	\$ 100.00	NNX
13	Rear end panel top garnish clips	1	\$ 60.00	\$ 30.00	NECV
14	Taillamp seal	2	\$ 60.00	\$ 40.00	NECV
15	Taillamp clips	2	\$ 60.00	\$ 120.00	NNX
16	Rear number plate w/casing	1	\$ 80.00	\$ 50.00	BRV
SPECIAL NETT TOTAL :				\$ 290.00	1,392.00

Nos.	LABOUR	S\$	
1	R&R tailgate component	\$ 80.00	150.00
2	R&R tailgate windscreen	\$ 120.00	250.00
3	R&R rear bumper reverse sensor	\$ 60.00	100.00
4	R&R rear exhaust pipe	\$ 150.00	150.00
5	Upholstery	\$ 300.00	300.00
6	Check wiring	\$ 30.00	100.00
7	Diagnostic reset fault code	\$ 120.00	300.00
8	Panel beating	\$ 1000.00	1,800.00
9	Rust proofing	\$ 200.00	200.00
10	Spray painting	\$ 600.00	1,800.00
LABOUR TOTAL :		\$ 2010.00	5,150.00

27/8/2021 30/8/2021
 1550 hrs 1250 hrs
 TOLIM TOLIM
 Min Min
 Survey Resurvey

Part by Part repair
 Repair days 7

PARTS TOTAL : \$ 23,693.23
 SPECIAL NETT TOTAL : \$ 1,392.00
 LABOUR TOTAL : \$ 5,150.00
 GRAND TOTAL : \$ 30,235.23

PARTS 10774.88
 SN 290.00
 Labour 2010.00
 13074.88

COR \$13,074.00

TOLIM Min
 8/9/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: