

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

KH INSTRUMENTATION PTE LTD
50 BUKIT BATOK ST 23 #05-17
SINGAPORE 659578

Contact : 81837608, 81929818

TP111
Ashes.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Repair Code : CLM16913

Date in : 26/08/2021

Vehicle Num. : GBE4381Z

Model : NISSAN NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

Chassis/Eng# : VSKYBAM20Z0115473/K9KC400D054928

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR AXLE <i>new</i>	1	1997.00	✓ 1,997.00
REAR BUMPER <i>delcd</i>	1	485.90	✓ 485.90
REAR BUMPER SIDE RETAINER L/R <i>RH cancd</i>	2	37.20	37.20 74.40
REAR RH FENDER <i>dented.</i>	1	1636.10	✓ 1,636.10
REAR RH FENDER INNER AIR VENT <i>cancd</i>	1	78.30	✓ 78.30
REAR RH SHOCK ABSORBER <i>new</i>	1	88.40	✗ 88.40
REAR RH SLIDING DOOR <i>Repair</i>	1	919.90	✗ 919.90
REAR RH TAILGATE 'DCI' EMBLEM <i>new</i>	1	42.10	✗ 42.10
REAR RH TAILGATE HINGE (LOWER) <i>new</i>	1	49.80	✗ 49.80
REAR RH TAILLAMP <i>cancd</i>	1	262.10	✓ 262.10
REAR RH WHEEL BEARING <i>delcd</i>	1	794.00	412 794.00
REAR RH WHEEL RIM <i>new</i>	1	305.40	✗ 305.40
REAR RH WHEEL RIM HUB CAP <i>at</i>	1	168.60	✓ 168.60
Subtotal before discount			6,902.00
Percentage discount 10%			690.20
Sub-total 1			6,211.80
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
REAR RH FENDER STICKER <i>new</i>	1	450.00	280 450.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

KH INSTRUMENTATION PTE LTD
 50 BUKIT BATOK ST 23 #05-17
 SINGAPORE 659578

Contact : 81837608, 81929818

ESTIMATE

Repair Code : CLM16913

Date in : 26/08/2021

Vehicle Num. : GBE4381Z

Model : NISSAN NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC

Chassis/Eng# : VSKYBAM20Z0115473/K9KC400D054928

REAR RH SLIDING DOOR STICKER <i>new</i>	1	350.00	<i>250</i>	<i>350.00</i>
REAR RH TAILGATE 3D STICKER <i>new</i>	1	350.00	<i>570</i>	<i>350.00</i>
REAR RH TAILLAMP CLIPS - SET <i>new</i>	1	25.00	<i>10</i>	<i>25.00</i>
REAR RH TYRE <i>Not new</i>	1	300.00	<i>+</i>	<i>300.00</i>
Subtotal before discount				1,525.00
Percentage discount 0%				0.00
Sub-total 2				1,525.00
Parts-total				7,736.80

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,560.00
Parts & Labour Total	10,296.80

total : 4682.18

n/s : 3.7K

*** This is a computer-generated document which requires no signature.***

1340

60.00

80 300.00

80 100.00

60 100.00

100 900.00

600 1,000.00

60 100.00

Adrian L

n/s 26/08/21

05 Days.