

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCG6128D

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 EMBLEM <i>ne</i>	90892-4EA0A	94.40		
2 EMBLEM-REAR <i>Xnn</i>	90890-4EA0A	64.90		
3 A LOCK LIFT <i>Xnn</i>	90502-4EA1B	173.20		
4 RUBBER-DUM <i>ne</i>	Q2716-89900	63.80		
5 REAR W/SCREEN SEALANT <i>ne</i>	SEALANT - 4			80.00
6 GLASS-TAIL GATE <i>ne phh?</i>	90300-4EA0D	1089.00		
7 DOOR BACK <i>bt</i>	K0100-4EAAC	3368.90		
8 BRACKET-BUMPER RH <i>? xnn</i>	85220-4EA0A	38.90		
9 BRACKET-BUMPER LH <i>? xnn</i>	85221-4EA0A	38.90		
10 RETAINER-BUMPER RH <i>? xnn</i>	79184-4EA0A	25.70		
11 RETAINER-BUMPER LH <i>? xnn</i>	79185-4EA0A	25.70		
12 CANOE RIVET BUMPER \$7.10 EA X 02 <i>ne</i>	76882-0M000	14.20		
13 CLIP BUMPER \$8.00 EA X 03 <i>ne</i>	85284-JD00A	24.00		
14 GROMMET BUMPER \$2.70 EA X 04 <i>ne</i>	63846-5V000	10.80		
15 CLIP BUMPER \$1.30 EA X 04 <i>ne</i>	01553-05933	5.20		
16 GROMMET BUMPER \$2.40 EA X 02 <i>ne</i>	01281-00111			4.80
17 STAY ASSY-REAR RH <i>? xnn</i>	H5210-4EAMA	141.00		
18 STAY ASSY-REAR LH <i>? xnn</i>	H5211-4EAMA	141.00		
19 REINF-BUMPER RR <i>? bt</i>	H5030-4EAMA	691.50		
20 ENERGY ABSORBER <i>? xnn</i>	85090-4EA0B	155.60		
21 FINISHER-REAR BUMPER TOW <i>? xnn</i>	85071-4EA0A	18.80		
22 FASCIA-RR BUMP <i>de</i>	85022-4EA0H	876.40		
23 CLIP END PANEL \$1.30 EA X 02 <i>? xnn</i>	01553-05323	2.60		
24 CLIP-FINISHER \$1.30 EA X 04 <i>? xnn</i>	01554-00181	5.20		
25 PLATE LUGGAGE REAR <i>? xnn</i>	84992-4EA0B	63.90		

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCG6128D

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
26 FENDER RH REAR ARC ? <i>for</i>	93828-4EA0A	540.50			
27 FENDER LH REAR ARC ? <i>for</i>	93829-4EA0A	540.50			
28 ORNAMENT ASSY RH ? <i>for</i> new	26560-JJ90A	61.90			
29 ORNAMENT ASSY LH ? <i>for</i>	26565-JJ90A	61.90			
30 CLIP ANTENNA \$3.80 EA X 02 <i>X</i> <i>nn</i>	01553-89900		7.60		
31 ANTENNA-SMART KEYLESS ? <i>for</i>	285E5-JK60A	53.50			
32 SUNDRIES <i>new</i>	NPN				
SUB TOTAL		8391.90	7.60	184.80	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1678.38	2.28	0.00	
GRAND TOTAL		6713.52	5.32	184.80	
OVERALL TOTAL		6903.64			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SCG6128D

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	/
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	120
3 RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	/
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 02	200.00	100
5 SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	/
6 UG10	RENEW ^{rear} FRONT WINDSHIELD GLASS ASSY.	240.00	/
7 ZZ/001	REPAIR END PANEL, LH REAR FENDER AND RENEW REAR BUMPER, TAILGATE @ 390	1950.00	1170
8 ZZ/002	S/PAINT REAR BUMPER (2 TONE), TAILGATE, END PANEL, LH REAR FENDER @ 250 x 3 + 100	1350.00	850
9 ZZ/003	TRANSFER TAILGATE MECHANICAL PARTS TO NEW DOOR	80.00	/
10 ZZ/004	R/I REAR DVR TO ASSSIT REPAIR	120.00	/
11 ZZ/005	CHECK LIGHTING	48.00	/
TOTAL LABOUR CHARGES		4608.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SCG6128D

TOTAL LABOUR CHARGES	4608.00
TOTAL SPARE PARTS CHARGES	6903.64
GRAND TOTAL	11511.64 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :

SURVEYED DATE :

AUTHORIZED DATE :

EXCESS CLAUSE : 0.00

LIABILITY : 0.00

REMARKS :

Resur - 4p 900x0068
31/08/21 @ 1030
5 days
Resur before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

16-Sep-2021

INS/IC/LAW/0216/2021

MS FIRST CAPITAL INSURANCE LTD
30 ROBINSON ROAD
#16-01 CITY HOUSE
Singapore 068877

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SCG6128D
POLCY NO. : -

Further to our claim we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

Replacement of Damaged Items


1	SENSOR-REVERSE nw 	\$250.00 S/N
2		
3		
4		
5		
6		
7		
8		
9		
10		

TOTAL \$ 250.00

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully

TAN CHONG MOTOR SALES PTE LTD


LAWRENCE TEO
Insurance Claim Dept

Cc: Surveryor