

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 AAS Kaki Bukit Centre #04-01 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 200913013D

TO : AXA

DATE : 26/08/2021

ATTENTION : MOTOR CLAIMS DEPT

JOB TYPE : T/P CLAIM

ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SDY1311S

MODEL : MAZDA 3

Justin

CHASSIS NO

ACCIDENT DETAILS DATE : 26-Aug-21

TIME : 05:30HRS

THIRD PARTY REQUESTOR / CONTACT JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>3 all</i>	1	\$ 1,155.30	\$ 1,155.30
2	BOOT LID LOGO <i>1 new</i>	1	\$ 80.50	\$ 80.50
3	BOOT LID EMBLEM 'MAZDA' <i>the new</i>	1	\$ 55.00	\$ 55.00
4	BOOT LID EMBLEM 'SKYACTIVE TECHNOLOGY' <i>the new</i>	1	\$ 58.00	\$ 58.00
5	BOOT LID EMBLEM '3' <i>the new</i>	1	\$ 50.00	\$ 50.00
6	REAR BUMPER <i>Behind</i>	1	\$ 1,055.20	\$ 1,055.20
7	REAR BUMPER HOCK <i>the new</i>	1	\$ 80.00	\$ 80.00
8	REAR BUMPER ALTERNATIVE <i>Local Antenna. Sensor</i> DAMAGED	1	\$ 180.00	\$ 180.00
9	REAR BUMPER REFLECTOR <i>the new</i>	2	\$ 86.20	\$ 172.40
10	REAR BUMPER SIDE RETAINER <i>the new</i>	2	\$ 62.40	\$ 124.80
11	REAR BUMPER TOWING COVER <i>the new</i>	2	\$ 90.50	\$ 181.00
12	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 573.60	\$ 573.60
13	REAR BUMPER REVERSE SENSOR <i>Damaged</i>	4	\$ 280.30	\$ 1,121.20
14	REAR END PANEL <i>Repair</i>	1	\$ 655.20	\$ 655.20
15	REAR END PANEL TOP GARNISH <i>cracked</i>	1	\$ 211.50	\$ 211.50

TOTAL PRICE \$ 5,753.70

LESS 20% \$ 1,150.74

SUB TOTAL PRICE \$ 4,602.96

SPECIAL NETT ITEMS

2145.1

1716.08

S.N:200

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00 ✓
2	REAR END PANEL INSULATION SEAL <i>Neu</i>	1	\$ 120.00	\$ 120.00 +
3	REAR END PANEL TOP GARNISH CLIP (SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00 ✓
		40	TOTAL	\$ 160.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	<i>500</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	<i>400</i>	
3	TUFF COAT	\$ 150.00	<i>50</i>	
4	WIRING CHECK	\$ 120.00	<i>30</i>	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	<i>50</i>	

TOTAL

\$2,390.00

ESTIMATE REPORT

TOTAL PARTS COS : \$ 4,762.96
TOTAL LABOUR CO : \$ 2,390.00
TOTAL REPAIR COS : \$ 7,152.96

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM :

NO OF DAYS :

FAX :

*Address L/S 27/08/21.
04 Days.*

*Total: 298608
L/S: 2.31c.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: