

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0690/2021/JT
DATE : 25-Aug-21
WIP : 41303

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/8/21
YOUR INSURED VEH NO : GN 5282 M

NTUC INCOME INSURANCE CO - CLAIMS DEPARTMENT

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSE

SINGAPORE 189556

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LOW BAK HIANG BUCK
ADDRESS : BLK 6 ST GEORGE'S LANE
#09-205
SINGAPORE 320006
TELEPHONE : HP +65 90058855
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900110620-01
VEHICLE NO : **SMM 4868 P**
MODEL CODE : A5 SB 2.0 TFSI
MODEL YEAR : 28/6/2019
ENGINE NO : CVK 080218
CHASSIS NO : WAUZZZF52KA054222
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Aug-21
PLACE OF ACCIDENT : FOWLIE ROAD AND JOO CHIAT
ROAD JUNCTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMM 4868 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	
3	TO RESPRAY REAR BUMPER.	\$ 1,000.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 2,752.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 4868 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,504.00	
2	REAR BUMPER FIXING PARTS	1	\$ 165.00	
3	REAR BUMPER SECURING STRIP	1	\$ 223.00	
4	REAR BUMPER CHROME TRIM	1	\$ 1,016.00	
5	REAR BUMPER REFLECTOR - LH / RH	2	\$ 82.00	
6	REAR BUMPER CARRIER	1	\$ 940.00	
7	REAR BUMPER CARRIER SEAL	2	\$ 28.00	
8	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 46.00	
9	REAR BUMPER SENSOR	2	TBC	
10	REAR BUMPER SENSOR SEAL RING	4	\$ 14.00	
11	SUNDRIES		\$ 200.00	
TOTAL SPARE PARTS		:	\$ 5,218.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	
GRAND TOTAL		:	\$ 7,970.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-24/08/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT