

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Cecilia

Quotation

DATE : 26.08.2021
 VEH NO : SKZ8769X
 MODEL : Mitsubishi Attrage
 D O A : 25.08.2021
 YR REF : SNA3118D

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKZ8769X (MITSUBISHI ATTRAGE)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	708.00 ✓
2	Rear Bumper Side Holder - RH <i>Dmgd</i>	1	34.00 ✓
3	Rear Bumper Inner Air Guide - RH <i>crushed</i>	1	48.00 ✓
4	Rear Bumper Reflector - RH <i>new</i>	1	32.00 x
5	Rear End Panel <i>Repair</i>	1	449.00 x
6	Tail Lamp - RH <i>lit</i>	1	276.00 ✓
7	Rear Fender - RH <i>Distorted</i>	1	798.00 ✓
8	Rear Fender Inner Shield - RH <i>new</i>	1	98.00 ✓
9	Rear Windscreen Moulding <i>new</i>	1	105.00 ✓
10	Front Bumper <i>Behind</i>	1	706.00 ✓
11	Front Bumper Side Holder - RH <i>Dmgd</i>	1	38.00 ✓
12	Front Bumper Fog Lamp - RH <i>new</i>	1	263.00 x
13	Front Bumper Fog Lamp Cover - RH <i>new</i>	1	119.00 x
14	Front Bumper Fog Lamp Chrome Moulding - RH <i>lit</i>	1	115.00 ✓
15	Head Lamp - RH <i>crushed</i>	1	755.00 ✓
16	Front Fender - RH <i>Repair</i>	1	538.00 x
17	Front Fender Emblem - RH <i>new</i>	1	74.00 ✓

3755
3379.50

10%
 Less 20%

5,156.00
 (1,031.20)
 \$ 4,124.80

S/NETT ITEMS

1	Rear Bumper Clips <i>new</i>	1 set	\$ 30.00 ✓
2	Reverse Sensor <i>new</i>	1	\$ 280.00 x
3	Rear Fender Inner Shield Clips - RH <i>new</i>	1	\$ 20.00 ✓
4	Rear Windscreen Sealant <i>new</i>	1	\$ 60.00 ✓
5	Rear Wheel Rim - RH <i>lit</i>	1	\$ 700.00 <i>480</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SKZ8769X (MITSUBISHI ATTRAGE)

6	Front Bumper Clips <i>nee</i>	1 set	\$	30.00 ✓
			\$	1,120.00
Total Parts			\$	5,244.80

LABOUR CHARGE - REAR PORTION

1	To knocking & pull out rear portion & renew above parts	\$	1,400.00 700
2	To putty & spray up paint works	\$	1,200.00 800
3	To check wiring	\$	50.00 ✓
4	To remove reverse sensor	\$	100.00 30
5	To spray tuff coat	\$	150.00 60
6	To remove rear windscreen	\$	180.00 120
7	To remove upholstery	\$	150.00 60
8	To perform wheel alignment	\$	150.00 80

LABOUR CHARGE - FRONTPORTION

1	To knocking & pull out front portion & renew above parts	\$	600.00 350
2	To putty & spray up paint works	\$	600.00 400
3	To check wiring	\$	50.00 30
Total Labour			\$ 4,630.00

Grand Total \$ 9,874.80

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6678.50
L/s : 5350
08 Days.