

ASS. REC. BY:

TGLim

REF:

CC4/LPC21009009/BB43

Jasper

ASSIGNMENT

From:

Date:

30/8/2021

Veh No:

GBC 6181G

Yr Regn:

18/4/2013

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBC 6181G

Make:

Toyota Hiace

C.C. 2982

Colour:

Orange

A/C: Insured / Std / NI / NA

Sp. Reading

209905

T/Radio: Insured / Std / NI / NA

Eng/No:

1Kd2290097

C/No:

JTFHT02P30-014313

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F: 195/15


R: 195/15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

24,000/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date:

Person Contacted:

Front

R/Bal.

5

mm

Rear

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

25/8/2021

D.O.I.

30/8/2021

Survey held at

Deam Auto Pro

Des. of Damages: PIR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 3,000/- - 4,000/-

Recommended car is LS \$3750.00

TGLim Mue
29/9/2021

MV 24,000/-

PV 8,875/-

NV 15,125/-

Date/Time, File Pass to?



Preli. Report

1)

Date/Time, File Return to?



Final Report

2)

Rep. Format:

Lump Sum / L.B.I. /

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **GBC 6181 G**
Made : Toyota Hiace
Year : 2013
Chassis No : 1KD2290097

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper	1	\$ 548.30	\$ 375.40 548.30
2	Front Bumper Side Retainer	2	\$ 60.00 298.90	\$ 120.00 597.80
3	Headlamp LH	1	\$ 754.20	\$ 340.00 754.20
4	Headlamp Panel	1	\$ 148.60	\$ 148.60
5	Front Door LH	1	\$ 975.80	\$ 520.00 975.80
6	Front Door Weatherstrip	1	\$ 148.00	\$ 148.00
7	Front Door Inner Lock	1	\$ 315.20	\$ 315.20
8	Front Door Hinge	2	\$ 105.80	\$ 211.60
9	Front Door Pillar LH	1	\$ 923.30	\$ 923.30
10	Front Step Panel LH	1	\$ 240.60	\$ 240.60
11	Front Step Panel Garnish LH	1	\$ 187.40	\$ 187.40
12	Side Mirror Assy LH	1	\$ 870.00	\$ 599.10 870.00
13	Front Knuckle Arm LH	1	\$ 451.20	\$ 451.20
14	Front Knuckle Arm Bearing LH	1	\$ 298.00	\$ 298.00
15	Front Lower Arm LH	1	\$ 378.20	\$ 378.20
16	Front Upper Arm LH	1	\$ 396.70	\$ 396.70
17	Front Shock Absorber LH	1	\$ 213.20	\$ 213.20
18	Front Control Arm LH	1	\$ 242.00	\$ 242.00

BRV
NECV
BRV
NDX
DDV
NDX
NDX
NDX
BRV
NDX
JMV
NDX

Parts Sub Total : \$ 2252.50 7,900.10
Discount : \$ 563.13 1,975.03
PARTS TOTAL : \$ 5,925.08

1689.38

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00 <i>80.00</i>
2	Front Bumper Clips	1	\$ 50.00	\$ <i>30.00</i> 50.00
3	Front Bumper Lower Lip (Fibre)	1	\$ 650.00	\$ <i>500.00</i> 650.00
4	Front Corner Panel LH (Fibre)	1	\$ 400.00	\$ <i>258.20</i> 400.00
5	Headlamp Outer Chrome Garnish	1	\$ <i>NEC</i> 350.00	\$ <i>205.40</i> 350.00
6	Front Door Sealant	1	\$ 100.00	\$ 100.00
7	Front Door Company Sticker	1	\$ 60.00	\$ <i>NOT NEC</i> 60.00
8	Front Door Outer Garnish (Carbon Fibre)	1	\$ 400.00	\$ <i>98.00</i> 400.00
9	Front Step Panel Sealant	1	\$ 100.00	\$ 100.00
10	Front Step Panel Garnish Clips	1	\$ 50.00	\$ 50.00
11	Side Mirror Outer Chrome Garnish	1	\$ 380.00	\$ <i>102.65</i> 380.00
12	Front Rim	1	\$ 650.00	\$ 650.00
13	Front Tyre	1	\$ 480.00	\$ 480.00
14	Front Rim Cap	1	\$ 280.00	\$ <i>126.80</i> 280.00
SPECIAL NETT TOTAL :				\$ <i>4,030.00</i>

1321.05

Nos.	LABOUR	S\$
1	R&R Front Door Component	\$ 80.00 <i>150.00</i>
2	R&R Front Under Carriage	\$ 120.00 <i>300.00</i>
3	R&R Front Tyre & Balancing	\$ 100.00 <i>100.00</i>
4	Wheel Alignment	\$ 60.00 <i>180.00</i>
5	Check Wiring	\$ 30.00 <i>100.00</i>
6	Uplostery	\$ 300.00 <i>300.00</i>
7	Panel Beating	\$ 800.00 <i>1,400.00</i>
8	Rust Proofing	\$ 200.00 <i>200.00</i>
9	Spray Painting	\$ 600.00 <i>1,400.00</i>
LABOUR TOTAL :		\$ <i>4,130.00</i>

1690.00

PARTS TOTAL : \$ 5,925.08
SPECIAL NETT TOTAL : \$ 4,030.00
LABOUR TOTAL : \$ 4,130.00
GRAND TOTAL : \$ 14,085.08

Parts 1689.38
SN 1321.05
Labour 1690.00

4700.43

940.09

3760.34

LS 3750/2

TGim
29/9/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Survey 30/8/2021
Resurvey 31/8/2021
Lump sum repair
Repair days 5
1210hrs
1210hrs
TGim
M