

22/9/2021
Survey & repairChang to
27/9

BMW Dealer

Performance Motors LimitedA Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 1 of 5

Estimate No. : b1 59305
Date Estimated : 26/08/2021
Prepared By : Chua Kee Sin**- ESTIMATE REPAIR FOR -**
Jason Tan Wee Peng (Jason Chen Weip
Blk 75 Anchovale Crescent
#11-11

Singapore 544662

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJD7192T	WBA8E36080NT89466	22/07/2016	318iA/4Dr	85920

DESCRIPTION

Replace rear bumper include remove attachment etc

Painting rear bumper

To check electrical wiring system and lighting at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

Sundries.

VALUE

850 1,275.00

986 1,038.00

168 177.00

168 177.00

80/? 150.00

Total Labour 1: 2,817.00

DESCRIPTION

REAR BUMPER CENTRE GUIDE ? x 150
 REAR BUMPER CARRIER (ECE) ? x 150
 REAR BUMPER TOWING EYE COVER PRIMED x 150
 REAR BUMPER BLACK TRIM STRIP ? x 150
 REAR BUMPER PANEL PRIMED (LINES) de
 (S/L) LH PROTECTION FOIL ? x 150
 (S/L) RH PROTECTION FOIL ? x 150
 SET MOUNTING PDC/PMA SENSOR REAR ? x 150
 DECOUPLING RING PDC TORQUE CONVERTE ? x 150
 BUMPER PDC SENSOR (A89 IMPERIALBLAU) ? x 150
 (DG/SL) ADHESIVE SET K6 ? x 150

QTY	PRIC	VALUE
1	153.50	153.50
1	470.25	470.25
1	43.70	43.70
1	83.00	83.00
1	1,184.75	1,184.75
1	10.75	10.75
1	10.75	10.75
1	67.65	67.65
4	5.15	20.60
4	371.20	1,484.80
1	53.05	53.05

Total Parts : 3,582.80

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 59305
 Date Estimated : 26/08/2021
 Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJD7192T	WBA8E36080NT89466	22/07/2016	318iA/4Dr	85920

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 2nd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 27/09/21 @ 1030 Excess S\$ _____Surveyor's Name RASUL Sign _____Surveyor's Tel 900010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Labour 1	:	2,817.00
Parts	:	3,582.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	447.99
Grand Total	:	6,847.79

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **