

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. PREETI BHART SHERI
BLK 209 PASIR RIS ST 21 #04-338
SINGAPORE 510209

Attention : Motor Claim Department

Contact : 97101842 65835424

Estimate : ES001510

Date : 24/08/2021

Vehicle Num. : EY 5499X

Make/Model : TOYOTA ESTIMA

Chassis/Eng# : ACR507071132

Accident Date : 24/08/2021

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1pc	BOOTLID <i>Distorted</i>		<i>1406.</i> 1,939.50
2.	1pc	BOOTLID HANDLE <i>crushed</i>		271.75 ✓
3.	1pc	BOOTLID REFLECTOR LH <i>crushed</i>		371.50 ✓ <i>281</i>
4.	1pc	BOOTLID REFLECTOR RH <i>crushed</i>		371.50 ✓ <i>281</i>
5.	1pc	BOOTLID REFLECTOR CENTRE <i>missing</i>		271.48 ✓
6.	1pc	REAR END PANEL <i>Dented</i>		755.40 ✓
7.	1pc	REAR END PANEL TOP GARNISH <i>del d</i>		371.50 <i>246</i>
8.	10pc	REAR END PANEL GARNISH CLIPS <i>crushed</i>	3.50	35.00 ✓
9.	1pc	REAR BUMPER <i>Deformed</i>		571.75 ✓
10.	1pc	REAR BUMPER REFLECTOR LH <i>3 new</i>		121.10 +
11.	1pc	REAR BUMPER REFLECTOR RH <i>3 new</i>		121.10 +
12.	1pc	REVERSE SENSOR <i>Dented</i>		250.00 ✓
13.	1pc	BOOTLID LOCK <i>Dented</i>		450.00 <i>355</i>
14.	1pc	REAR BUMPER RETAINER <i>3 new</i>		171.48 +
15.	1pc	REAR BUMPER RETAINER RH <i>3 new</i>		171.48 +
16.	1pc	BOOTLID INNER DOOR BOARD <i>crushed</i>		731.10 <i>458</i>
17.	1pc	TOYOTA EMBLEM <i>new</i>		61.50 ✓
18.	1pc	TOWING COVER <i>new</i>		61.50 +
19.	1pc	SPARE TYRE PANEL <i>new</i>		731.35 +
20.	1pc	SPARE TYRE BOARD <i>new</i>		971.75 +
21.	1pc	ESTIMA EMBLEM <i>new</i>		98.00 ✓
22.	1pc	BOOTLID HINGE LH <i>3 new</i>		191.10 +
23.	1pc	BOOTLID HINGE RH <i>3 new</i>		191.10 +
24.	1pc	BOOTLID ABSORBER RH		371.20 +

5316.88

3987.66

CONTINUE / ...

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. PREETI BHART SHERI
BLK 209 PASIR RIS ST 21 #04-338
SINGAPORE 510209

Attention : Motor Claim Department

Contact : 97101842 65835424

Estimate : ES001510

Date : 24/08/2021

Vehicle Num. : EY 5499X

Make/Model : TOYOTA ESTIMA

Chassis/Eng# : ACR507071132

Accident Date : 24/08/2021

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1pc	BOOTLID ABSORBER LH		371.20
	1pc	WIPER MOTOR		971.45
		List Total S\$:		10,996.19
1.	1pc	SPECIAL NETT ITEMS : NO PLATE (METAL)	25.	25.00
		Special Nett Total S\$:		25.00
		LABOUR :		1,600.00
		TO KNOCKING, JACKING, WELDING ETC		1,600.00
		SPRAY PAINTING ON BOOTLID, BUMPER, REAR END PANEL		50.00
		SPARE TYRE PANEL, FENDER RH & LH		120.00
		WIRING		
		APPLY ANTI RUSH		
		Labour Total S\$:		3,370.00

Total S\$: 14,391.19

LEE SHENG AUTO PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total : 5702.66

L/S: A.S.K.

06 Days