



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Ref: CS/AWA21009014/Evf3e2 Date: 08/12/2021  Code: AWA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XB 8814X	Veh. Inspected	SJW 9199L
Policy No.	BVFCB0013452102	Coverage (\$)	0.00
Claim No.	NSV2100109/HLF	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	27/08/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA STREAM	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JHMRN68809C200458	Colour	GREY
Odometer	128292 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	5 mm
L/H Front Tyre	205/55 R16	PIRELLI	5 mm
R/H Rear Tyre	205/55 R16	PIRELLI	5 mm
L/H Rear Tyre	205/55 R16	PIRELLI	5 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	17/08/2021	Inspection Date	30/08/2021
Survey held at	BIS AUTOMOBILES PTE LTD 30 TEBAN GARDENS CRESCENT, SINGAPORE 608927		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	