

BIS Automobiles Pte Ltd

Company Reg No: 201908617D
GST Reg No: 201908617D
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **A0038**

Invoice Name & Address:

Allied World Assurance Company Ltd
No.60 Anson Road
08-01
Singapore 079914

Customer Name & Address:

Miss Teo Choo Hong
Na

Singapore

Email: june.teo@ych.com

Inv. Printed By: VIC Service Advisor: Vikneswaran Naidu

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
P 24890	0	0		29/09/2021	13:18	1
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SJW9199L	C200458	Honda Stream RSZ	01/01/2021	29/09/2021	0	
Job Description						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
1	SUN	Removing and replacing all accident damage parts		1,350.00	1.00		0.00	1,350.00
2	SUN	Spray painting front bumper panel and front hood		900.00	1.00		0.00	900.00
3	SUN	Clear fault after repair and code the headlight		100.00	1.00		0.00	100.00
4	SUN	Sundry items		100.00	1.00		0.00	100.00
5		Bumper front - BR 430		1.00	473.00	EACH	0.00	473.00
6		Left side head lam X-AA cracked 480 (-50% net)		1.00	539.00	EACH	0.00	539.00
7		Right side head la X-AA cracked 480 (-50% net)		1.00	539.00	EACH	0.00	539.00
8		Front Bumper lower X-AA cracked 38		1.00	79.20	EACH	0.00	79.20
9		Front Bumper lower X-AA cracked 38		1.00	88.00	EACH	0.00	88.00
10		Front bumper reinf X nn		1.00	0.00	EACH	5.00	
11		Left retainer X nn		1.00	19.80	EACH	0.00	19.80
12		Right retainer X nn		1.00	19.80	EACH	0.00	19.80

V	Rate	Service/Goods	GST

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.

BIS Automobiles Pte Ltd

Company Reg No: 201908617D
GST Reg No: 201908617D
30 Teban Gardens Crescent, Singapore 608927
Tel: +65 65667666 Fax: +65 65659098



ESTIMATE

Account No. **A0038**

Invoice Name & Address:

Allied World Assurance Company Ltd
No.60 Anson Road
08-01
Singapore 079914

Customer Name & Address:

Miss Teo Choo Hong
Na

Singapore

Email: june.teo@ych.com

Inv. Printed By: VIC Service Advisor: Vikneswaran Naidu

W.I.P. No.	Job No.	Document No.	Appointment Type	Invoice Date	Time	Page
P 24890	0	0		29/09/2021	13:18	2
Reg No.	Chassis No.	Model	Reg Date	Date In	Mileage	
SJW9199L	C200458	Honda Stream RSZ	01/01/2021	29/09/2021	0	
Job Description						

No	Code	Description of Goods / Services	Con %	Qty.	Unit Price	Unit	Disc %	Net Total
13		Headlamp housing b x nn		1.00	43.56	EACH	0.00	43.56
14		Headlamp housing b x nn		1.00	43.56	EACH	0.00	43.56
15		Front bumper reinf x nn		1.00	237.60	EACH	0.00	237.60
16		Front Grille x nn cracked. 230		1.00	303.60	EACH	0.00	303.60
17		Front grille chrom x nn 195		1.00	257.00	EACH	0.00	257.00

931
+ 11%
1024.10
480
850
2354.10

Steve (LKK)
30/8/21

without Prejudice
3 days
P/P
Resurvey Before
cost plus 11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	V	Rate	Service/Goods	GST	Net	
Parts	S	2,643.12	5093.12	356.52	5,093.12	
Surcharge		0.00			356.52	
Labour		2,450.00			5,449.64	
Sublet		0.00			0.00	
Menus		0.00			5,449.64	

Customer's Signature

Authorized Signature

CASH/NETS/CHEQUE/AMEX/VISA/MASTER No:

N.B. Goods sold are not returnable.