



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21009016/Eqf3e2	
			Date: 19/10/2021	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YQ 2387K
	Policy No.	DH0M110174502001	Coverage (\$)	0.00
	Claim No.	M11D13572109	Excess (\$)	800.00
	Assign From	JOSEPHINE WONG	Assign Date	27/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	HINO XZU710R	c.c	4009
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JHHUCV3F90K033778	Colour	WHITE
	Odometer	99010 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/85 R16	BRIDGESTONE	5 mm
	L/H Front Tyre	195/85 R16	BRIDGESTONE	5 mm
	R/H Rear Tyre	195/85 R16	BRIDGESTONE	5 mm
	L/H Rear Tyre	195/85 R16	BRIDGESTONE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/08/2021	Inspection Date	07/09/2021
	Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks				
	A)THE MARKET VALUE IS S\$84,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	