

NOT AUTHORIZED
 11 Pay @ 3200k
 Recovery After Paint
 3 days

EM Solution Pte Ltd

160 Sin Ming Drive, (Sin Ming Autocity), #03-18/19, Singapore 575722

H/P: 9004 2254 (Derek Keh) Tel: 6456 0226 Fax: 6458 4500

Email: emautosolution@singnet.com.sg

Vehicle number: GBE5200G

Vehicle Made & Model: NISSAN CABSTAR

Qty	List Items	Amount \$
1	Tailgate <i>1399.20</i>	B1 1,639.60 ✓
1	Tailgate emblem "NISSAN"	M 211.50 ✓
1	Tailgate lower member	B1 586.50 ✓
1	Tailgate stopper - RH	N 48.60 ✓
1	Tailgate stopper bracket - RH	D1 180.90 ✓
1	Taillamp - RH <i>225</i>	B1 283.50 ✓
1	Taillamp panel - RH <i>168.40</i>	B1 186.40 ✓
1	Rear exhaust pipe	R 441.60 X
1	Rear exhaust mounting	S 28.60 X
1	Rear sidegate lock hinges - RH	N 195.60 X
Sub-total		3,802.80
Less 10%		380.28
Total List		3,422.52

Special Nett Items

- 1 Rear sticker "70 KM/H"
- 1 Rear sticker "13 PAX"
- 1 Rear step panel
- 1 set Rear reverse sensor
- 1 set Rear reflective markings
- 1 Rear no. plate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

M	10.00	—
M	10.00	—
R	250.00	X
CMA	280.00	200sm
M	180.00	801. —
S	40.00	X
Total Special Nett		770.00

Acknowledged by Repairer
 Signature:
 Date:

Labour charges

To check rear electrical wiring	50.00	20k
To respray undercoating	60.00	✓
To respray painting and etc	800.00	540k
Panel beating, cut, weld remove & replacing above parts	800.00	600k
Total Labour	1,710.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 5,902.52