

WORKSHOP 99 AUTO SERVICES

Blk 9 Sin Ming Road
#01-34 Sin Ming Industrial Estate
Singapore 575644.

T. (65) 6458 8460
F. (65) 6455 5379
E. workshop99@rocketmail.com

Date	28-Jun-2021	Ref.:	TP Claim
Owner Particulars			
Name	NK Décor		
# Nos	10, Anson Road	Mobile No.	97976811
Address	#05-16 International Plaza Singapore 079903		
Vehicle Particulars			
Number	GBG4202Y		
Model	TOYOTA DYNA 150 5MT		
Engine	1KD2731057		
Chassis	JTFAT35Y10K208475		
Year	10-Aug-17		
Accident Details			
Date	24 June, 2021		
Time	09:35 hrs		
Place	Sims Drive		
Insured With			
Insurance	China TaiPing Insurance (Singapore) Pte Ltd		
Policy No.	DMCVSNA00071162001		
Expiry	10 August, 2021		
Driver Particulars			
Name	Ng Jonus		
Nric Nos.	S9836448Z	Mobile No	9976811
Address	Blk 157 Serangoon North Ave 1 #04-863 Singapore 550157		
Parts & Labour Costs			
	List Prices		
	Nett Prices		
	Special Nett Prices		
	Labour Charges		
	Number of working days		
COMMENTS		COMPANY STAMP	
1. This Estimate is based on visual Inspections of visible damages on the above vehicle.			
2. We will keep you informed if further damages are found.			
3. This Estimate is valid for 30 days only.			
		Signature	

	Estimate Cost Of Repairs	Vehicle #	GBG4202Y
--	--------------------------	-----------	----------

QTY	DESCRIPTIONS	UNITS	AMOUNTS
1 pce	Front bumper ? ✓ BR		\$ 848.90
2 pcs	Front bymper brackets repair x		\$ 126.40
1 pce	Front bumper n/s side grille x n n		\$ 87.30
1 pce	N/s Headlamp assy -		\$ 1,178.90
1 pce	Radiator grille - 4 BR		\$ 595.70
			2454.60
			-25%
			1840.95
			\$ 2,837.20
		Less 25%	\$ 709.30
			\$ 2,127.90
	Nett		
1 pce	Front no plate ✓ GBR.		\$ 50.00
			25
	Labour		
	To remove lamps, necessary wirings		\$ 40.00
	Labour to remove damaged parts, check, repairs, replace and refit same		\$ 480.00
	To spray painting replacement parts and repaint damaged sections with welded portions in and outside, including putty.		\$ 580.00
	To rust proofing damaged portions and replacement parts	610	\$ 80.00
			2475.95
		L/S - 1980.76	
		= 2000	
		Total	\$ 3,357.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 Days.
Lumpsum Repair
After repair photos
Genc @ Qiang.
17/8/21.