



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21009031/Gny3e2	
			Date: 21/12/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6332L	Veh. Inspected	GBG 4202Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/06/21/2053	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	27/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTFAT35Y10K208475	Colour	SILVER	
Odometer	68136 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/85 R15	KENDA	6 mm	
L/H Front Tyre	195/85 R15	KENDA	6 mm	
R/H Rear Tyre	155 R12	YOKOHAMA	6 mm	
L/H Rear Tyre	155 R12	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/06/2021	Inspection Date	17/08/2021	
Survey held at	WORKSHOP 99 AUTO SERVICES BLK 9 SIN MING ROAD #01-34 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	