



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462, Tel no. : 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM <i>Sumner</i>			S1000020 / TPCLAIM		Ms Chan Yin Ha 3 Pandan Valley #11-302A Singapore 597627 Mobile: 96196856		
			Document No. 0				
			Document Date 27/08/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ASE30R	AEZLZQ S1	28/11/2016	SLK9288C	0	20062	64TP/SLK9288C/260821
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHBA1D2805032851		8ARZ047787	60	Wally Tan G H	--/--/----		0.00 --/--/----
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50	80.00
2	B	BP-LAB3 TRANSFER R/F AND R/R DOORS COMPONENT AND MECHANISM TO NEW DOOR SHELLS. (NETT) <i>866 x 2</i>					1732.00 ✓
3	B	BP-LAB3 REMOVE/REFIX RHS ROCKER MLDG. (NETT) <i>(photo)</i>				433.00 ✓	
4	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN RHS DOOR CENTRE PILLAR, RHS ROCKER PANEL AND FIT NEW PARTS. <i>866 x 1.5</i>				1299	2598.00 ✓
5	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR. <i>3 x 742</i>				2226	2597.00
6	Z	BP-SLANT SUPPLY SEALANT (NETT) <i>120 x 2</i>					200.00 ✓
7	S	BP-SUBLET TO RESET ECU & REPROGRAMME. (NETT)					216.50 ✓
8	1	L67001-53120 PANEL, DOOR FR RH <i>DD</i>	1.00	1361.30			1361.30
9	2	L75929-53010 TAPE, BLACK OUT FR RH <i>111</i>	1.00	69.90			69.90
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 Pandan Crescent
 Singapore 128462. Tel no. 6631 1388


ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Chan Yin Ha			
			Document No. 0		3 Pandan Valley #11-302A Singapore 597627			
			Document Date 27/08/2021		Mobile: 96196856			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2016	ASE30R	AEZLQ S1	28/11/2016	SLK9288C	0	20062	64TP/SLK9288C/260821	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBA1D2805032851		8ARZ047787	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
10	3	L75968-53010	TAPE, BLACK OUT FR	APC	1.00	38.40		38.40
11	4	L67863-53030	WEATHERSTRIP, FR	APC	1.00	62.30		62.30
12	5	L75755-53020	MOULDING, RR DOOR RH	APC	1.00	75.40		75.40
13	6	T68710-12151	R/FRT UPP DOOR HINGE,	APC	1.00	98.20		98.20
14	7	T68730-12120	R/FRT DOOR LOW HINGE,	APC	1.00	112.00		112.00
15	8	L67003-53070	PANEL SUB-ASSY, RR	APC	1.00	1138.70		1138.70
16	9	L75951-53010	TAPE, BLACK OUT RR	APC	1.00	38.40		38.40
17	0	L75937-53010	TAPE, BLACK OUT RR	APC	1.00	65.90		65.90
18	1	L67857-53020	L/R EAR DOOR PROTECTOR,	APC	1.00	55.60		55.60
19	2	L75761-53020	MOULDING, RR DOOR	APC	1.00	71.40		71.40
20	3	L90269-04051	RIVET	APC	14.00	1.50		21.00
21	4	T68750-20122	HINGE ASSY, RR DOOR,	APC	1.00	99.60		99.60
22	5	T68770-52031	R/RR LOW DOOR HINGE,	APC	1.00	87.90		87.90
23	6	L58741-53030	PROTECTOR, QUARTER RH	APC	1.00	29.00		29.00
24	7	L75862-53060	PROTECTOR, ROCKER	APC	1.00	47.90		47.90
25	8	L75862-53070	PROTECTOR, ROCKER	APC	1.00	26.90		26.90
26	9	L76921-53010	PROTECTOR, SIDE	APC	2.00	21.10		42.20
27	0	L76921-53020	PROTECTOR, SIDE	APC	1.00	21.10		21.10
28	1	L75864-50020	PROTECTOR, ROCKER	APC	4.00	11.60		46.40
29	2	L75867-33030	CLIP, ROCKER PANEL	APC	11.00	11.00		121.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature	Charge Summary	Total			
			Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less			
					Amount Due			

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 Pandan Crescent
 Singapore 128462, Tel no. 6631 1388

ESTIMATE

Account Details		Account No.		Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM		Ms Chan Yin Ha				
		Document No. 0		3 Pandan Valley #11-302A Singapore 597627				
		Document Date 27/08/2021		Mobile: 96196856				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers Wip No. Order No. / Remarks			
2016	ASE30R	AEZLZQ S1	28/11/2016	SLK9288C	0 20062 64TP/SLK9288C/260821			
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In Collected On			
JTHBA1D2805032851		8ARZ047787	60	Wally Tan G H	--/--/---- 0.00 --/--/---- 0.00			
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
30	3	L76923-52021 RETAINER, SIDE			6.00	6.60		39.60
31	4	L75867-30120 CLIP			1.00	11.00		11.00
<i>Stev (LKK)</i> <i>1/9/21, 10.00am</i> <i>Wally PL</i> <i>6 days</i> <i>P/P</i> <i>My Bel sy</i>								
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company								
For & on behalf of		Customer's Signature		Charge Summary		Total 11,637.60		
Borneo Motors (Singapore) Pte Ltd		Date: _____		Please acknowledge receipt of vehicle		GST 7.00% 814.63		
				Parts		3,781.10		
				Labour		7,640.00		
				Sublet		216.50		
				Lubrication/Fluid		0.00		
				Others		0.00		
Amount Due						12,452.23		

Customer Copy