

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

GLEN YEOW JUN HUNG
BLK 25 PASIR RIS ST 72 #05-11
SINGAPORE 518766

Contact : 90938383

TP AXA
Ceilia

ESTIMATE

Repair Code : CLM15298

Date in : 26/08/2021

Vehicle Num. : SMV8383Y

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11100387/L15B4020389

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR RH DOOR <i>Dented</i>	1	930.60	✓ 930.60
REAR RH DOOR BLACK TAPE <i>ph</i>	1	35.00	✓ 35.00
REAR RH DOOR INNER TRIM BOARD <i>Amolded</i>	1	498.00	✓ 498.00
REAR RH DOOR MECHANISM LOCK <i>Ne m</i>	1	210.00	+ 210.00
REAR RH DOOR TRANSPARENT STICKER <i>Neu</i>	1	35.00	✓ 35.00
REAR RH DOOR WEATHER STRIP <i>Ne m</i>	1	98.00	+ 98.00
REAR RH DOOR WEATHER STRIP (LOWER) <i>Ne m</i>	1	65.00	+ 65.00
REAR RH DOOR WEATHER STRIP (VERTICAL) <i>Ne m</i>	1	65.00	+ 65.00
REAR RH FENDER <i>Reps</i>	1	884.40	+ 884.40
REAR RH FENDER ARCH GARNISH <i>cut</i>	1	195.00	✓ 195.00
REAR RH FENDER INNER SHIELD <i>Ne m</i>	1	153.40	+ 153.40
REAR RH SHOCK ABSORBER <i>Ne m</i>	1	385.00	+ 385.00
REAR RH WHEEL BEARING <i>payd</i>	1	263.50	— 263.50
REAR RH WHEEL RIM <i>cut</i>	1	813.00	<i>400/50</i> 813.00
ROCKER GARNISH RH <i>delnd</i>	1	377.50	— 377.50

*** This is a computer-generated document which requires no signature.***

page 1

2334.6

1867.68

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

GLEN YEOW JUN HUNG

BLK 25 PASIR RIS ST 72 #05-11

SINGAPORE 518766

Contact : 90938383

ESTIMATE

Repair Code : CLM15298

Date in : 26/08/2021

Vehicle Num. : SMV8383Y

Model : HONDA VEZEL 1.5X CVT

Chassis/Eng# : RU11100387/L15B4020389

	Subtotal before discount	5,008.40
Percentage discount 20%		1,001.68
	Sub-total 1	4,006.72
REAR RH 215/60R16 TYRE <i>Ne m</i>	1	380.00 <i>x</i> 380.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>Ne</i>	1	50.00 <i>30</i> 50.00
REAR RH FENDER ARCH GARNISH CLIPS - SET <i>Ne</i>	1	40.00 <i>20</i> 40.00
REAR RH FENDER INNER SHIELD CLIPS - SET <i>Ne m</i>	1	50.00 <i>x</i> 50.00
ROCKER GARNISH RH CLIPS - SET <i>Ne</i>	1	50.00 <i>30</i> 50.00
	Subtotal before discount	570.00
Percentage discount 0%		0.00
	Sub-total 2	570.00
	Parts-total	4,576.72

LABOUR

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

2,380.00

Parts & Labour Total

6,956.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

document which requires no signature.***

page 2

total: 3427.68

h/s: 2.7K

04 Days

Adrian L
h/s 30/08/21