

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

27-Aug-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1352 L

1 pc	Front bumper / <i>Dis</i>	\$	811.11	
1 pc	Front bumper emblem X <i>NN</i>	\$	27.80	X
2 pcs	Front bumper n/s & o/s side bracket \$32.51 / <i>cut</i>	\$	65.02	
1 pc	Front bumper o/s upper bracket / <i>BT</i>	\$	92.60	
1 pc	Front bumper o/s support bracket / <i>NN</i>	\$	37.01	
1 pc	Front bumper o/s fog light garnish X <i>NN</i>	\$	25.00	X
1 pc	Front o/s fog lamp X <i>NN</i>	\$	840.90	X
1 pc	Front bumper reinforcement X <i>NN</i>	\$	636.40	X
1 pc	Bonnet / <i>BT</i>	\$	1,220.40	
1 pc	Support panel / <i>BR</i>	\$	1,292.20	
1 pc	Front o/s head lamp / <i>CRA</i>	\$	1,531.57	
1 pc	Front o/s fender / <i>one</i>	\$	514.02	
1 pc	Front o/s fender inner shield / <i>IN</i>	\$	176.72	
1 pc	Front o/s fender signal lamp / <i>cut</i>	\$	32.10	
1 pc	o/s mirror assy / <i>Dis</i>	\$	742.49	
1 pc	Front o/s door / <i>Buc</i>	\$	1,723.60	
2 pcs	Front o/s hinges @ \$36.10 / <i>BT</i>	\$	72.20	
1 pc	Washer tank / <i>Re</i>	\$	51.40	
1 pc	Washer tank motor X <i>NN</i>	\$	75.00	X
1 pc	Front o/s mud flap / <i>cut</i>	\$	47.45	
2 pcs	Front n/s & o/s rim @\$246.00 / <i>cut</i>	\$	492.00	
2 pcs	Front n/s & o/s lower arm @\$811.34 / <i>DM</i>	\$	1,622.68	
2 pcs	Front n/s & o/s shock absorber @\$611.56 X <i>NN</i>	\$	1,223.12	X
2 pcs	Front n/s & o/s tie rod end @\$72.50 X <i>NN</i>	\$	145.00	X
2 pcs	Front n/s & o/s ball joint @\$91.90 X <i>NN</i>	\$	183.80	X
2 pcs	Front n/s & o/s knuckle arm @\$873.88 / <i>DM</i>	\$	1,747.76	
2 pcs	Front n/s & o/s knuckle bearing @\$349.60 X <i>NN</i>	\$	699.20	X
2 pcs	Front n/s & o/s stabilizer link @\$88.50 X <i>NN</i>	\$	177.00	X
		\$	16,305.55	12272.33
Less 20%		\$	3,261.11	
		\$	13,044.44	9817.86

S/NETT

1 set	Front bumper clips /	\$	48.00	
1 pc	Front o/s fender sticker /	\$	30.00	
1 set	Front o/s fender inner shield clips /	\$	28.00	
1 set	o/s door stickers /	\$	100.00	
2 pcs	Tyre @\$200.00 / <i>cut</i>	\$	400.00	200
			406	

7-Aug-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1352 L

Sundry	\$	50 00	X n n
Towing Fee	\$	50 00	-
To check front o/s wheel alignment	\$	80 00	60
To adjust/focus front n/s & o/s head lamps	\$	80 00	30
To dismantle / refit the front n/s & o/s undercarriage	\$	300 500 00	7 (300)
To top up aircon gas	\$	120 00	-
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180 00	X n n
To dismantle & refit the inner components of the front o/s door into the new shell door	\$	150 00	60
To labour charge for dismantle and renew the accident damaged parts including knock-out, straighten, repair, reshape and adjust of the front o/s wheel house, rear o/s door	\$	1 000 00	720
To putty and spray painting on front bumper, front o/s fender, front o/s wheel house, front o/s door, rear o/s door, o/s rocker panel.	\$	1 200 00	1100
To apply rustproofing on the repaired and replaced panels	\$	150 00	60
	\$	17 210 44	2500

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

12723.86

-20%: 10200

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES

7 Days
Unpenn repair
After repair photos.
Came Qi of.
27/8/21.

UK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary costs must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: