

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

27-Aug-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1352 L

1 pc	Front bumper / Dis	\$ 811.11
1 pc	Front bumper emblem X NN	\$ 27.80
2 pcs	Front bumper n/s & o/s side bracket \$32.51 / Cut	\$ 65.02
1 pc	Front bumper o/s upper bracket / BT	\$ 92.60
1 pc	Front bumper o/s support bracket /	\$ 37.01
1 pc	Front bumper o/s fog light garnish X NN	\$ 25.00
1 pc	Front o/s fog lamp ?	\$ 840.90
1 pc	Front bumper reinforcement X NN	\$ 636.40
1 pc	Bonnet / BT	\$ 1,220.40
1 pc	Support panel / BR	\$ 1,292.20
1 pc	Front o/s head lamp / C/A	\$ 1,531.57
1 pc	Front o/s fender /	\$ 514.02
1 pc	Front o/s fender inner shield / IN	\$ 176.72
1 pc	Front o/s fender signal lamp / Cut	\$ 32.10
1 pc	o/s mirror assy / Dis	\$ 742.49
1 pc	Front o/s door / Buc	\$ 1,723.60
2 pcs	Front o/s hinges @ \$36.10 / BT	\$ 72.20
1 pc	Washer tank / Re	\$ 51.40
1 pc	Washer tank motor X NN	\$ 75.00
1 pc	Front o/s mud flap / Cut	\$ 47.45
2 pcs	Front n/s & o/s rim @\$246.00 / Cut ?	\$ 492.00
2 pcs	Front n/s & o/s lower arm @\$811.34	\$ 1,622.68
2 pcs	Front n/s & o/s shock absorber @\$611.56 ?	\$ 1,223.12
2 pcs	Front n/s & o/s tie rod end @\$72.50 ?	\$ 145.00
2 pcs	Front n/s & o/s ball joint @\$91.90 ? ?	\$ 183.80
2 pcs	Front n/s & o/s knuckle arm @\$873.88 ?	\$ 1,747.76
2 pcs	Front n/s & o/s knuckle bearing @\$349.60 ?	\$ 699.20
2 pcs	Front n/s & o/s stabilizer link @\$88.50 ?	\$ 177.00
		\$ 16,305.55
	Less 20%	\$ 3,261.11
		\$ 13,044.44

S/NETT

1 set	Front bumper clips /	\$ 48.00
1 pc	Front o/s fender sticker /	\$ 30.00
1 set	Front o/s fender inner shield clips /	\$ 28.00
1 set	o/s door stickers /	\$ 100.00
2 pcs	Tyre @\$200.00 / Cut	\$ 400.00 200

7-Aug-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1352 L

Sundry	\$	50.00	X n n
Towing Fee	\$	50.00	-
To check front o/s wheel alignment	\$	80.00	60
To adjust/focus front n/s & o/s head lamps	\$	80.00	30
To dismantle / refit the front n/s & o/s undercarriage	\$	500.00	?(30)
To top up aircon gas	\$	120.00	-
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	X n n
To dismantle & refit the inner components of the front o/s door into the new shell door	\$	150.00	60
To labour charge for dismantle and renew the accident damaged parts including knock-out, straighten, repair, reshape and adjust of the front o/s wheel house, rear o/s door	\$	1,000.00	720
To putty and spray painting on front bumper, front o/s fender, front o/s wheel house, front o/s door, rear o/s door, o/s rocker panel.	\$	1,200.00	1100
To apply rustproofing on the repaired and replaced panels	\$	150.00	60
	\$	17,210.44	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

7 Days
Unpaid repair
After repair photos.
Came to it of.
27/8/21.

UK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary costs must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: