

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

27-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6829 B

1 pc	Bootlid CRDi / MCL	\$	29.00
1 pc	Boot lid rubber weatherstrip / MCL	\$	96.00
1 pc	Boot lid lower garnish / MCL	\$	290.00
1 pc	o/s tail lamp / CPA CPA	\$	421.00
1 pc	o/s reflector X CPA NA	\$	350.00
1 pc	Rear bumper / De	\$	696.00
1 pc	Rear bumper lower cover / O/S	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 RH / CA, LHX NA	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$	36.00
1 pc	Rear bumper reflector o/s / CPA	\$	46.00
1 pc	Exhaust pipe X NA	\$	1,009.00
		\$	4,102.00
Less 10%		\$	410.20
		\$	3,691.80

S/NETT

1 set	Rear bumper clips / MCL	\$	48.00
1 set	End panel inner garnish clips X NA	\$	30.00
1 set	Bootlid lower garnish clips / MCL	\$	60.00
1 set	Bootlid stickers / MCL	\$	100.00
1 set	Reverse sensor X AM	\$	280.00
1 pc	Rear o/s fender sticker / MCL	\$	60.00

27-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6829 B

Towing Fee	\$	50.00	✓
Sundry <i>nn</i>	\$	50.00	X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	40
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. <i>nn</i>	\$	180.00	X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender etc	\$	950.00	360
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, rear o/s fender	\$	1,000.00	720
To apply rustproofing on the repaired and replaced panels. <i>nn</i>	\$	200.00	X
	\$	<u>6,819.80</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*4 Days.
4/5
After repair photos.
Gina Qi ap
27/8/21*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: