

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

27-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6829 B

1 pc	Bootlid CRDi / MCL	\$	29.00	✓
1 pc	Boot lid rubber weatherstrip / MCL	\$	96.00	✓
1 pc	Boot lid lower garnish / MCL	\$	290.00	✓
1 pc	o/s tail lamp / CRD CRA	\$	421.00	✓
1 pc	o/s reflector X CRD NN	\$	350.00	
1 pc	Rear bumper / De	\$	696.00	✓
1 pc	Rear bumper lower cover / D/S	\$	206.00	✓
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 RH / GA, LHX NN	\$	58.00	29
1 pc	Rear bumper inner sponge X NN	\$	114.00	
1 pc	Rear bumper reinforcement X CRA	\$	607.00	✓
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 X NN	\$	108.00	
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 X NN	\$	36.00	
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 X NN	\$	36.00	
1 pc	Rear bumper reflector o/s / CRA	\$	46.00	✓
1 pc	Exhaust pipe X NN	\$	1,009.00	
		\$	4,102.00	2420
		Less 10%	\$	410.20
			\$	3,691.80 2178

S/NETT

1 set	Rear bumper clips / MCL	\$	48.00	✓
1 set	End panel inner garnish clips X NN	\$	30.00	
1 set	Bootlid lower garnish clips / MCL	\$	60.00	✓
1 set	Bootlid stickers / MCL	\$	100.00	✓
1 set	Reverse sensor X NN	\$	280.00	
1 pc	Rear o/s fender sticker / MCL	\$	60.00	✓

268

27-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6829 B

Towing Fee	\$ 50.00	✓
Sundry <i>nn</i>	\$ 50.00	X
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00	40
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. <i>nn</i>	\$ 180.00	X
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender etc	\$ 950.00	360
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, rear o/s fender	\$ 1,000.00	720
To apply rustproofing on the repaired and replaced panels. <i>nn</i>	\$ 200.00	X
	<u>\$ 6,819.80</u>	1170

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

3616

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

-20%: 2850

*4 Days.
4/5
After repair photos.
Gma Q: ap
27/8/21*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: