

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal work to be carried out
- Supplemental survey must be resurveyed and is subject to final approval from Insurance Company

Longpac Motor Insured's Veh No : GBB6764E

Date of Accident : 24 August 2021

Acknowledged by Repairer

Signature:

Date:

Messrs Generic Print Pte Ltd

TP Longpac
Jasper



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Date : 25 August 2021

Estimate To Repair GBH4288U - Toyota Proace Comfort 1.6D M/T 6DR

Chassis No : YARVBBHVBGZ103542

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper <i>Repld</i>	\$ 850.00
02	1 pc	o/s rear bumper reflector <i>Mya Best</i>	\$ 150.00
03	1 pc	rear bumper reinforcement	\$ 580.00
04	2 ps	rear bumper side bracket @ \$85.00 <i>R14 Pm d</i>	\$ 170.00
05	1 pc	o/s tailgate <i>Repld</i>	\$ 2,350.00
06	1 pc	o/s tailgate lock <i>Repld</i>	\$ 300.00
07	1 pc	o/s tailgate inner trimboard <i>Repld Replaced</i>	\$ 250.00
08	1 pc	o/s tailgate weatherstrip <i>new</i>	\$ 85.00
09	1 pc	o/s tailgate PROACE emblem <i>new</i>	\$ 105.00
10	1 pc	o/s tailgate glass <i>Shattered</i>	\$ 890.00
11	1 pc	o/s tailgate inner trim <i>Repld</i>	\$ 180.00
12	1 pc	o/s taillamp <i>Repld</i>	\$ 330.00
			\$ 6,240.00
Less 25 %			\$ 1,560.00
			\$ 4,680.00
<u>SPECIAL NETT ITEMS</u>			
13	1 set	rear bumper parking sensor <i>Repld</i>	\$ 3,502.00
14	1 pc	Corporate sticker <i>new</i>	\$ 250.00
15	1 pc	o/s tailgate glass sealant <i>3 per</i>	\$ 50.00
16	1 pc	o/s tailgate glass inner seal	\$ 470.00
			\$ 4,272.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 60.00
02		To rust-proofing of the affected areas.	\$ 120.00
03		To remove and refit o/s tailgate glass.	\$ 80.00
04		To transfer of o/s tailgate fittings and perform water seepage test.	\$ 150.00
05		To reinstall of rear bumper parking sensor.	\$ 120.00
06		Putty and spray painting of the affected portion.	\$ 1,200.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 850.00
			\$ 2,580.00
Total			\$ 11,532.00

per: Adrian - Uek
26/08/2021 C/booh

total: 5667.50
A/S: A.S.K
26/08/21
04 Days.