

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592

Estimator Telephone Number : 68662623 Accident Reporting Number : 68662672

User ID PohSuan

Section A - Accident Details					
Registration Number	SHB432G				
Case Reference Number	TAX/08/21/2057				
Registration Date	3/9/2014				
Company Type	Strides Taxi Pte Ltd				
Make	ТОУОТА				
Model	PRIUS				
Name of Driver	NG WEE NGENG (HUANG HUIYIN)				
Type of Accident	Side Swipe				
Accident Date and Time	21/8/2021 6:04 PM				
Accident Reported Date and Time	24/8/2021 2:11 PM				
Is Surveyor Required?	Yes				
Survey by					
Vehicle is Towed Back?	No				
Towed Back Date and Time					
Replacement Vehicle issued?	No				
Job Card Number	24112021				
Special Instruction to ARC,if any	TP / FRONT LEFT LEFT PORTION / AIG - LKK				
Prepared Date and Time	25/8/2021 1:14 PM				
Chassis Number					
Mileage	1				
Work Shop	1				
Repair Completion Date and Time					

Section B - Summary of Repair Estimates							
Summary of Repair Estimates							
Quotation from ARC	Adjusted by Surveyor, if applicable						
\$676.00	\$200.00						
\$558.00	\$280.00						
\$2,954.90	\$0.00						
\$440.00	\$0.00						
\$4,628.90	\$480.00 (P/P)						
\$4,650.00							
5.0	2.0						
Tuck Foo Kok	RASUL (LKK) / AIG						
te 25/08/2021 4:47 PM	25/08/2021 4:09 PM						
Z	Res						
	LUMP SUM REPAIR / AFTER REPAIR PHOTO .						
	Quotation from ARC \$676.00 \$558.00 \$2,954.90 \$440.00 \$4,628.90 \$5.0						



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated : 03/09/2021 User ID PohSuan

Section C - Quotation and Accident Invoice Details							
Quotation Number	QN-2109-0073	Invoice Number					
Quotation Date	03.09.2021	Invoice Date					
Invoice Amount		Prepared Date					

Section D - Details of Repair Estimates						
Part 1 - Labour Works						
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable				
TO REPAIR FRONT LH PORTION	\$676.00	\$200.00				
Total Labour	\$676.00	\$200.00				

Part 2 - Spray Painting & Panel Beating Related Works							
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable					
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00					
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$80.00					
Total Spray Painting & Panel Beating	\$558.00	\$280.00					

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00 × NN		
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00 × NN		
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 × NN		
TO WASH AND VACUUM	\$60.00	\$0.00 × NN		
Total Other Costs	\$440.00	\$0.00		

Part Number	Portion	Stock Number	Part Name		List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		53876-	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
		47030			****	1.00.00				_
		81170-	HEAD LAMP LH	1.00	\$945.20	100.00	\$0.00	Replace	Old Damage	X
		47500	DUMPED EDT ADCORDED	0.00	£407.70	0.00	* 0.00	Dania	Nat Chian	- ^``
		52618-	BUMPER FRT ABSORBER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X
		47050 76851-	LOWER BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given	- 1
		47020	BUNIFER LIF FRI	0.00	φ139.00	0.00	\$0.00	Replace	Not Given	X
		53111-	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given	\dashv
		47040	Grazze, roadiraron	0.00	φο το.σο	0.00	Ψ0.00	Topiaco	140t Given	×
		81521-	LENS & BODY. FR TURN LH	1.00	\$511.80	100.00	\$0.00	Replace	Old Damage	7 ()
		47050			4000	1.00.00	V 0.00	, topiass	Join Damage	×
		81529-	BRACKET, FR TURN UPPER	0.00	\$24.40	0.00	\$0.00	Replace	Not Given	٦
		47040	LH					'		X
		81529-	BRACKET, FR TURN	0.00	\$26.00	0.00	\$0.00	Replace	Not Given	X
		47050	LOWER LH							
		81529-	BRACKET, FR TURN	0.00	\$58.20	0.00	\$0.00	Replace	Not Given	×
		47060	CENTER LH							
		81220-	FOG LAMP LH	0.00	\$280.10	0.00	\$0.00	Replace	Not Given	X
		12230			*****	1		<u></u>	<u> </u>	_
		53102-	BUMPER GRILLE SUB-ASSY,	1.00	\$311.10	100.00	\$0.00	Replace	Repair	×
		47020 52116-	LOWER BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	* 0.00	Danlasa	Not Given	_
			BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	l X
		47040 52128-	COVER, FR BUMPER HOLE	1.00	\$18.50	100.00	\$0.00	Replace	Repair	\dashv
		47903	LH	1.00	φ 10.50	100.00	φυ.υυ	Treplace	Izehaii	X
	+	57013-	ARM SUB-ASSY. FR BUMPER	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	\dashv
		47030	RH	0.00	Ψ200.40	10.00	\$5.00	Copiaco	THE CIVEL	X
		57014-	ARM SUB-ASSY. FR BUMPER	0.00	\$250.40	0.00	\$0.00	Replace	Not Given	٦.
		47030	LH				1,3.00			×
		52021-		0.00	\$498.40	0.00	\$0.00	Replace	Not Given	٦.,
		47023	FRT							X
		52611-	BUMPER ENERGY	0.00	\$78.80	0.00	\$0.00	Replace	Not Given	×
		47080	ABSORBER FRT							
		52161-	BUMPER CLIPS	0.00	\$1.61	0.00	\$0.00	Replace	Not Given	X
		16010							1	



STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 03/09/2021 User ID PohSuan

	52119- 47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair	x R
Total				\$4,562.91		\$0.00			

Added Spare Parts / Material Usage After Surveyor Signed off								
Part Number		Stock Number	Part Name	Quantity	List Price \$		Final Price (\$)	Surveyor Check
Total								

	0.00
+	200.00
+	280.00
	480.00