

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009057/UVCN2**Date:** 27/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00022372104

Claimant Vehicle No : SLW6959G **Insured Vehicle No :** XD6896L

Date of Loss: 26/08/2021 Nature of Claim: TP Claim No: SNM21D204765/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW6959G**

Make & Model: MAZDA 3, 1.5 SEDAN AT LED EU6 (A) Engine No: P520499258

Reg. Date: 27/02/2018 (Man. Year: 2018) Chassis No: JM6BN22A8J0208985

Colour: Red Odometer: 88042 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,273.10	3,889.28	11,383.82	74.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,920.00	1,730.00	47.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	18,923.10	5,809.28	13,113.82	69.30
Approved Total (Overridden) (\$\$)		4,600.00		
Nett Amount (\$\$)	18,923.10	4,600.00	14,323.10	75.69

INSPECTION

Date of Assignment: 29/08/2021

Date Inspected: 30/08/2021 Inspected At: Blk 15 Kaki Bukit Road 4,
Bartley Biz Centre,#01-53
Repairer: Zoom Autowerks Pte Ltd

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2021)
Parts:	143	MAZDA 3 1.5 SEDAN AT LED EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW6959G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	1,425.00 FL	*1,074.80 FL
2	1		*REAR BUMPER SIDE RETAINER	N/s Bent	130.00 FL	*65.00 FL
3	2		*REAR BUMPER BRACKET	Not Necessary	156.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	256.00 FL	*- FL
5	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	28.00 FL	*- FL
6	2		*REAR BUMPER CORNER BRACKET	Not Necessary	50.00 FL	*- FL
7	1		*SET REAR BUMPER SENSOR BRACKET	Not Necessary	68.00 FL	*- FL
8	1		*REAR BUMPER SENSOR HARNESS	Not Necessary	240.00 FL	*- FL
9	2		*REAR BUMPER TOW GARNISH	Not Necessary	30.00 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Bent	498.00 FL	*498.00 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*50.00 FL
12	1		*REAR BOOTLID PANEL	Dented	1,985.00 FL	*1,066.20 FL
13	1		*REAR BOOTLID INNER TRIM	Not Necessary	596.00 FL	*- FL
14	1		*REAR BOOTLID INNER LOCK	Not Necessary	485.00 FL	*- FL
15	1		*REAR BOOTLID CATCH	Not Necessary	68.00 FL	*- FL
16	1		*REAR BOOTLID LOGO	Necessary	75.00 FL	*58.50 FL
17	1		*REAR BOOTLID EMBLEM (MAZDA)	Necessary	74.00 FL	*32.00 FL
18	1		*REAR BOOTLID EMBLEM (ACTIVE)	Necessary	75.00 FL	*45.00 FL
19	2		*REAR BOOTLID LAMP	Not Necessary	1,590.00 FL	*- FL
20	1		*REAR BOOTLID WEATHER STRIP	Not Necessary	375.00 FL	*- FL
21	1		*REAR TAILLAMPS	N/s Cracked	2,050.00 FL	*915.00 FL
22	1		*REAR END PANEL	Dented	955.00 FL	*530.40 FL
23	1		*REAR END PANEL TOP GARNISH	Twisted	318.00 FL	*214.20 FL
24	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
25	2		*REAR SPARE TYRE SIDE SPONGE	Not Necessary	290.00 FL	*- FL
26	1		*REAR SPARE TYRE TOP GARNISH	Not Necessary	368.00 FL	*- FL
27	1		*REAR SPARE TYRE PANEL	Not Necessary	1,325.00 FL	*- FL
28	1		*REAR EXHAUST PIPE	Not Necessary	1,425.00 FL	*- FL
29	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	175.00 FL	*- FL
30	1		*REAR EXHAUST CHROME MUFFLER	Not Necessary	215.00 FL	*- FL
31	3		*REAR EXHAUST MOUNTING	Not Necessary	144.00 FL	*- FL
32	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
33	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*REAR SPARE TYRE PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
35	1		*REAR EXHAUST GUM	Not Necessary	120.00 FS	*- FS
36	1		*REAR NUMBER PLATE W/BASE GARNISH	Not Necessary	65.00 FS	*- FS
37	1		*SET REAR BUMPER SENSOR	Shorted	648.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,832.00	4,799.10
- List Item Discount on L Items 10.00/20.00% (\$\$)	1,558.90	909.82
Total Parts (\$\$)	15,273.10	3,889.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	800.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	900.00
3	TO REMOVE & INSTALL REAR EXHAUST TO FACILITATE REPAIRS	New	150.00	0.00
4	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
5	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS	New	150.00	60.00
6	TO REMOVE & INSTALL SPARE TYRE COMPARTMENT TRIM,GARNISH	New	150.00	80.00
7	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
8	TO RUST PROOF AFFECTED AREAS	New	200.00	60.00
Gross Labour Cost (\$\$)			3,650.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >