

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21009059/T1QF3E2

Date: 25/11/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SBS7442M

Insured Vehicle No : SMV2491H

Date of Loss: 25/08/2021

Nature of Claim: TP

Claim No: 9994228930SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS7442M**

Make & Model: VOLVO B9TL, 9.4 D (A)

Engine No: D99126257

Reg. Date: 27/09/2006 (Man. Year: 2006)

Chassis No: YV3S4H9226A114523

Colour: Green

Odometer: 798346 km

Engine Capacity: 9364 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	470.00	470.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	470.00	470.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	32.90	32.90	0.00	0.00
Nett Amount (S\$)	502.90	502.90	0.00	0.00

INSPECTION

Date of Assignment: 30/08/2021

Date Inspected: 31/08/2021

Inspected At:

Sbs Transit Ltd (Bedok) (HQ)

1470 BEDOK NORTH AVE 4

Singapore 489946

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CONTRACTOR LABOUR COST	New	470.00	470.00
			Gross Labour Cost (\$)	470.00
				470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >