

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asi Pacific Pte Ltd
Date: 25/01/2021
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLF2956E
CHASSIS NO : NSP1707034026
MAKE / MODEL : Toyota Sienta 1.5 x Auto
DATE OF ACCIDENT : 12/07/2019 22/01/2021
YOUR INSURED VEHICLE NUMBER : SGL8813Y
MILEAGE : 274649 km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	R/Rdoor SCR ✓ CR4	1PC	\$ 1,404.00	\$ 1,404.00 1,279
2	R/Rfender rubber pad ✓ SCR	1PC	\$ 280.00	\$ 280.00 86.5
3	R/Rdoor rubber pad ✓ SCR	1PC	\$ 390.00	\$ 390.00 147.5
LIST TOTAL S\$:				\$ 2,074.00 1,513
25.00% DISCOUNT S\$:				\$ 518.50 -25%
				\$ 1,555.50 1,134.75

	<u>LABOUR CHARGES</u>	
1	To labour charge for removing F/L door, R/Rdoor, rear bumper out to facilitate replacement of parts. Also repair R/L fender	\$ 900.00 500
2	To respray rear bumper, F/L door, R/R door and R/Rfender	\$ 1,200.00 600
3	Transfer tailgate mechanism	\$ 100.00 X
4	To configure keyless network security system back to factory specification	\$ 300.00 X
LABOUR TOTAL S\$:		\$ 2,500.00 1100 ✓
TOTAL S\$:		\$ 4,055.50
7% GST		\$ 283.89
GRAND TOTAL S\$:		\$ 4,339.39

Repair day - 3 days

LIS
 After paint photo
 Sun Pin(LHK)
 26/01/2021
 TP without pre-judge

1,134.75
 1,100
 2,234.75
 -20%
 1,787.8

21.5
 \$1,800
 3 days