



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

GST Reg No: MX-0869103-NO Business Reg No: 394773/00D

E-mail: nphauto@pacific.net.sg

Your Ref :

Page : 1/2

Our Ref : TP0060/08/21

Date : 27/08/2021

THIRD PARTY CLAIM

M/S : TAN WEE LIANG

BLK 601C TAMPINES AVE 9

#07-838

SINGAPORE 523601

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SLX2575B - MAZDA 2

INSURED : TAN WEE LIANG

DATE OF ACCIDENT : 27/08/2021

POLICY NO : MA015032

ENGINE# :

CHASSIS# :

*not Adhond
den
2/5 #3400
4 days.*

*Edun jrb Hb rep -
30/8/21*

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 front grille <i>CM</i>	1@	101.90	101.90	101.90 <i>2</i>
2 front grille chrome moulding <i>CM</i>	1@	166.00	166.00	166.00 <i>2</i>
3 front grille center logo	<i>17</i> 1@	33.50	33.50	33.50 <i>X</i>
4 front bumper with nose	<i>17</i> 1@	873.00	873.00	873.00 <i>C</i>
5 front bumper clips	<i>CM</i> 8@	5.90	5.90	47.20 <i>—</i>
6 front bumper air scoop grille	<i>SL2</i> 1@	92.00	92.00	92.00 <i>—</i>
7 front bumper side retainer RH	<i>CM</i> 1@	38.00	38.00	38.00 <i>—</i>
8 front bumper reinforcement <i>3rd</i>	1@	529.00	529.00	529.00 <i>—</i>
9 front headlamp assy RH	<i>SL20</i> 1@	580.00	580.00	580.00 <i>—</i>
10 front headlamp lower bumper retainer RH	<i>SL</i> 1@	42.00	42.00	42.00 <i>X</i>
11 front panel nose inner garnish top	<i>17</i> 1@	98.00	98.00	98.00 <i>X</i>
12 front wiper reserve tank	<i>SL</i> 1@	68.00	68.00	68.00 <i>—</i>
13 front wiper reserve tank motor	<i>17</i> 1@	79.00	79.00	79.00 <i>X</i>
14 front fender RH	<i>3rd</i> 1@	339.00	339.00	339.00 <i>—</i>
15 front fender inner cowling RH	<i>7th</i> 1@	68.00	68.00	68.00 <i>—</i>
16 front fender inner cowling clip	<i>SL</i> 8@	4.80	4.80	38.40 <i>—</i>
17 front radiator support panel fibre <i>CM</i>	1@	373.00	373.00	373.00 <i>✓</i>
				3,566.00
Less 20% <i>front bumper sponge Torn ✓ 8127 ✓</i>				-713.20
Total Material				\$2,852.80
Labour & Misc				
1 Remove & install f/bumper, f/grille, f/headlamp, f/fender, radiator support panel, knock wheel house panel, chassis member and restraighthen body & chassis.	<i>600</i> 750.00			
2 Spray painting.	<i>800</i> 1,000.00			
3 Check wiring system.	25.00 <i>—</i>			



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg



Your Ref :
Our Ref : TP0060/08/21

Page : 2/2
Date : 27/08/2021

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
4 Vacuum & top up gas.			11	100.00 X
				1,875.00
Total Labour				\$1,875.00
Nett Total Before Gst				\$4,727.80

Your faithfully

NPH AUTO SERVICE
(Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-34405
202
27524
4257.4
3405



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
 GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
 E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/1
 Our Ref : RP0460/09/21 Date : 06/09/2021

SUPPLEMENTARY

M/S : TAN WEE LIANG
 BLK 601C TAMPINES AVE 9
 #07-838
 SINGAPORE 523601

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SLX2575B - MAZDA 2
 INSURED : TAN WEE LIANG
 DATE OF ACCIDENT : 27/08/2021
 POLICY NO : MA015032

ENGINE# :

CHASSIS# :

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
Replacement of Parts				
1 front bumper sponge	10	127.00	127.00	127.00
Less 20%				-25.40
Total Material				\$101.60
Nett Total Before Gst				\$101.60

Your faithfully

NPH AUTO SERVICE
 (Manager)