



# 南方摩哆 Southern Motor

Business Reg. No: 234147/00L  
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762  
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

26-Aug-21  
AIG Asia Pacific Insurance Pte Ltd  
78 Shanton Way #07-16  
AIG Building  
Singapore (079120)

Dear Sirs,

**RE: Cost of repair to Honda CB400 – FBP7672G**

1pc of Meter	S\$	1,680.00
1pc of Clutch Lever		45.00
1pc of Handle Bar		145.00
1pc of Front Head Lamp		1,550.00
1pc of Mirror		95.00
1pc of Engine Guard		160.00
1pc of Gear Lever		140.00
1pc of Front Footrest		65.00
1Set of Rear Footrest		55.00
1Set of Footrest Bracket		225.00
1pc of Side Stand		90.00
1pc of Handle Balancer		35.00
1pc of Fuel Tank		1,580.00
1pc of CAM Cover		480.00
1pc of Gasket		65.00
1pc of Signal Light		75.00
1pc of Fork Oil Seal		60.00
		<hr/> 6,545.00
	Less 10%	654.50
		<hr/> 5,890.50
	Nett	5,890.50
	Transport	40.00
	IU	165.00
	Alignment Fork	100.00
	Rear Box	350.00
	Labor	350.00
		<hr/> <u>\$6,895.50</u>

Yours Faithfully,  
Southern Motor



Date: 26 Aug 2021

Southern Motor  
Blk 1006 Bukit Merah Lane 2  
#01-10  
Singapore 159762

Motor Claims Department  
AIG Asia Pacific Insurance Pte Ltd  
78 Shanton Way #07-16  
AIG Building  
Singapore 079120

Dear Sirs,

RE: ACCIDENT INVOLING FBP7672G AND SNA7914X ALONG  
Jalan Bukit Merah ON 02-08-2021 AT 12:30AM

Please be informed that the above-said motorcycle bearing registration no: FBP7672G was seriously damaged during the above-said accident and was beyond economic repair.

Kindly arrange for your surveyor to survey the above-mentioned motorcycle at Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762. (Tel:62730369)

Thanking you in advance,

Yours Faithfully,



Enc.