



# 南方摩哆 Southern Motor

Business Reg. No: 234147/00L  
Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762  
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
Acknowledged by Repairer  
Signature:  
Date:

26-Aug-21  
AIG Asia Pacific Insurance Pte Ltd  
78 Shanton Way #07-16  
AIG Building  
Singapore (079120)

Steve (LKK)  
30/8/21, 2-30pm  
8322 8813

wr PL  
LIS  
MALSY  
3 days

Dear Sirs,

## RE: Cost of repair to Honda CB400 - FBP7672G

|                                 |           |          |          |        |
|---------------------------------|-----------|----------|----------|--------|
| 1pc of Meter                    | ✓ CUT     | SS       | 1,680.00 | 1550 ✓ |
| 1pc of Clutch Lever             | ✓ CUT     |          | 45.00    | ✓      |
| 1pc of Handle Bar               | ✓ BT      |          | 145.00   | ✓      |
| 1pc of Front Head Lamp          | ✓ BT      |          | 1,550.00 | 1500 ✓ |
| 1pc of Mirror                   | ✓ CUT     |          | 95.00    | ✓      |
| 1pc of Engine Guard             | ✓ OD      |          | 160.00   | ✓      |
| 1pc of Gear Lever               | ✓ BT      |          | 140.00   | 90 ✓   |
| 1pc of Front Footrest           | ✓ MIS     |          | 65.00    | ✓      |
| 1Set of Rear Footrest           | ✓ CUT     |          | 55.00    | ✓      |
| 1Set of Footrest Bracket        | ✓ BT      |          | 225.00   | ✓      |
| 1pc of Side Stand               | ✓ BT      |          | 90.00    | ✓      |
| 1pc of Handle Balancer          | ✓ CUT     |          | 35.00    | ✓      |
| 1pc of Fuel Tank (Local repair) | ✓ * / OD  | nett 400 | 1,580.00 |        |
| 1pc of CAM Cover (Local repair) | ✓ * / CUT | nett 150 | 480.00   |        |
| 1pc of Gasket                   | ✓ N/C     |          | 65.00    | 40 ✓   |
| 1pc of Signal Light             | ✓ CUT     |          | 75.00    | ✓      |
| 1pc of Fork Oil Seal            | ✓ N/C     |          | 60.00    | ✓      |

P- 4230 Local repair - 550

- 10%

3807

L - 855

= 5212

LIS - 4169-60

= 4150

Less 10%

Nett

Transport

IU CUT

Alignment Fork

Rear Box CUT

Labor

6,545.00  
654.50  
5,890.50  
40.00 ✓  
165.00 ✓  
100.00 50  
350.00 ✓  
350.00 250  
\$6,895.50

Yours Faithfully,  
Southern Motor

