

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0705/2021/ZK
DATE : 30-Aug-21
WIP : 41808

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 02/09/2021

YOUR INSURED VEH NO : SMF 6316 P

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ANG HOCK SOON
ADDRESS : 8 SUFFOLK WALK
#16-11
SINGAPORE 307465
TELEPHONE : HP +65 9171 1907
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : GA520064/1
VEHICLE NO : **SGW 699 S**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFSI S
MODEL YEAR : 5/1/2018
ENGINE NO : CVK 050327
CHASSIS NO : WAUZZZF59JA048206
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Aug-21
PLACE OF ACCIDENT : 2ND LEFT LANE ON PIE TOWARDS SLIP ROAD BKE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED FRONTAL LABOUR CHARGES FOR ACCIDENT VEHICLE SGW 699 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNES FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$	480.00	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$	800.00	
3	TO RENEW AIRCON CONDENSER,ADDITIONAL RADIATOR,RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$	1,700.00	
4	TO DIMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S.N \$	560.00	
5	TO DISMANTLE AND RENEW FRONT BUMPER , BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK-CARRIER AND	\$	4,800.00	
6	TO RESPRAY FRONT BUMPER,BONNET,HINGES AND BOTH FRONT DOORS.	\$	4,000.00	
TOTAL LABOUR CHARGES (FRONT)		:	\$ 12,340.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED REAR LABOUR CHARGES FOR ACCIDENT VEHICLE SLL SGW 699 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	S/N \$	280.00	
3	TO RENEW REAR WINDSCREEN	S/N \$	480.00	
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	S/N \$	400.00	
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	S/N \$	200.00	
TOTAL LABOUR CHARGES (REAR)		:	\$ 1,720.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGW 699 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING.RE-ORGANIZE CRASH MANAGEMENT CIMPONENTS.REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	
7	TO RESPRAY REAR BUMPER , REAR LID . HINGES AND REAR END PANELLING	\$ 3,500.00	
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 384.00	
9	PAINT COATING (BY OWNER)	TBC	
TOTAL LABOUR CHARGES (FRONT AND REAR)		: \$ 20,744.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 699 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,251.00	
2	FRONT BUMPER FIXING SET	1	\$ 407.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	
4	FRONT BUMPER GRILLE - LOWER CENTER	1	\$ 196.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 228.00	
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 126.00	
7	FRONT RADIATOR GRILLE	1	\$ 2,326.00	
8	FRONT BUMPER SENSOR SUPPORT - LH / RH	2	\$ 102.00	
9	FRONT BUMPER RADIATOR GRILLE COVER - UPPER	1	\$ 189.00	
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 948.00	
11	FRONT PARKING AID SENSOR	2	TBC	
12	FRONT PARKING AID SENSOR SEAL	4	\$ 14.00	
13	FRONT BUMPER WIRING SET	1	\$ 510.00	
14	HORN - LH / RH	2	\$ 252.00	
15	HORN BRACKET - LH / RH	2	\$ 58.00	
16	FRONT BUMPER REINFORCMENT FOAM	1	\$ 124.00	
17	FRONT BUMPER CARRIER	1	\$ 845.00	
18	FRONT BUMPER TOP COVER	1	\$ 127.00	
19	CAUTION STICKER	1	\$ 14.00	
20	AIR CONDITIONER STICKER	1	\$ 8.00	
SUB TOTAL SPARE PARTS		:	\$ 8,796.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 699 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 137.00	
22	FRONT BUMPER SUPPORT - LH / RH	2	\$ 58.00	
23	POP RIVET	4	\$ 4.00	
24	FRONT BONNET	1	\$ 3,312.00	
25	RETAINING CLIP	3	\$ 4.00	
26	CAP NUT	6	\$ 24.00	
27	FRONT BONNET ATTACHMENT PART	1	\$ 123.00	
28	FRONT BONNET HINGE - LH / RH	2	\$ 838.00	
29	FRONT BONNET IMPACT PROTECTION - LH / RH / CENTER	3	\$ 84.00	
30	FRONT BONNET INSULATION	1	\$ 343.00	
31	FRONT FENDER COVER - LH / RH	2	\$ 144.00	
32	FRONT BONNET STRIKER - LH / RH	2	\$ 100.00	
33	FRONT BONNET LOCK	2	\$ 427.00	
34	FRONT BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	
35	FRONT BONNET CABLE COVER	1	\$ 10.00	
36	FRONT BONNET RELEASE CABLE	1	\$ 58.00	
37	FRONT BONNET HOOD RELEASE	1	\$ 14.00	
38	FRONT BONNET LOCK CABLE - RH	1	\$ 74.00	
39	PLENUM CHAMBER COVER - RH	1	\$ 97.00	
40	FRONT HEADLIGHT - LH / RH	1	\$ 15,804.00	
SUB TOTAL SPARE PARTS		:	\$ 21,713.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 699 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT HEADLIGHT LIFT CYLINDER - LH / RH	2	\$ 396.00	
42	HEADLIGHT WASHER SPRAY	1	\$ 86.00	
43	LOCK CARRIER	1	\$ 1,016.00	
44	RADIATOR LOWER SUPPORT - LH / RH	2	\$ 76.00	
45	AIR COOLER	1	\$ 622.00	
46	AIR CON CONDENSER	1	\$ 622.00	
47	AIR TEMPERATURE SENSOR BRACKET	1	\$ 19.00	
48	RADIATOR	1	\$ 904.00	
49	COOLANT	6	\$ 142.00	
50	RADIATOR AIR DUCT - LH / RH	2	\$ 63.00	
51	RADIATOR INNER AIR DUCT - LH / RH	2	\$ 32.00	
52	RADIATOR AIR DUCT - LOWER	1	\$ 22.00	
53	RADIATOR FAN RING	1	\$ 267.00	
54	RADIATOR FAN	1	\$ 2,318.00	
55	FRONT DOOR CHROME TRIM - LH / RH	2	\$ 328.00	
56	FRONT DOOR WINDOW SLOT CHROME TRIM - LH / RH	2	\$ 798.00	
57	REAR BUMPER	1	\$ 2,504.00	
58	REAR BUMPER FIXING SET	1	\$ 165.00	
59	REAR BUMPER SECURING STRIP	1	\$ 223.00	
60	REAR BUMPER CHROME TRIM	1	\$ 1,016.00	
SUB TOTAL SPARE PARTS		:	\$ 11,619.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 699 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	REAR LIGHT REFLECTOR - LH / RH	2	\$ 82.00	
62	REAR BUMPER CARRIER	1	\$ 940.00	
63	HEXAGON	1	\$ 4.00	
64	REAR BUMPER SEAL	2	\$ 28.00	
65	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 46.00	
66	REAR INNER TAIL LIGHT - LH / RH	2	\$ 2,038.00	
67	REAR LID	1	\$ 3,818.00	
68	REAR LID ATTACHMENT PART	1	\$ 153.00	
69	REAR LID LOCK	1	\$ 248.00	
70	REAR LID LOCK COVER	1	\$ 13.00	
71	REAR WEATHERSTRIP	1	\$ 236.00	
72	REAR LID LOCKELECTRIC LOCK WITH CAMERA	1	\$ 1,389.00	
73	REAR LID STRIKER	1	\$ 66.00	
74	REAR LICENSE BRACKET CLIP	2	\$ 3.00	
75	ADHESIVE	1	\$ 19.00	
76	AUDI EMBLEM	1	\$ 156.00	
77	A5 EMBLEM	1	\$ 99.00	
78	TFSI EMBLEM	1	\$ 99.00	
79	REAR WINDSCREEN	1	\$ 1,168.00	
80	PRIMER	1	\$ 20.00	
SUB TOTAL SPARE PARTS		:	\$ 10,625.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGW 699 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	REAR BRAKE LIGHT	1	\$ 576.00	
82	LICENCE PLATE LIGHT	2	\$ 101.00	
83	REAR PANEL TRIM	1	\$ 360.00	
84	REAR TAIL LIGHT TRIM - LH / RH	2	\$ 60.00	
85	FRONT / REAR NO PLATE	S/N	\$ 120.00	
86	REAR WINDSCREEN SEALANT	1	\$ 200.00	
87	SUBDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 54,570.00	
TOTAL LABOUR CHARGES		:	\$ 20,744.00	
GRAND TOTAL		:	\$ 75,314.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT