



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21009075/Dvf3e2	
			Date: 07/02/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 701E	Veh. Inspected	SH 8208Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/08/21/2063	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	30/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI I40	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KMHLB41UMHU097354	Colour	BLUE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/50 R16	WEST LAKE	5 mm
	L/H Front Tyre	205/50 R16	WEST LAKE	5 mm
	R/H Rear Tyre	205/50 R16	WEST LAKE	5 mm
	L/H Rear Tyre	205/50 R16	WEST LAKE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, O/S FRONT AND O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/08/2021	Inspection Date	31/08/2021
	Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate		
	Repairer	BIFROST AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	