

TK MOTOR WORKSHOP
1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL : 96273323 FAX 68442641
CO.REG NO: 53049097-L

TAY SIEW LENG

DATE : 20/09/2021

BLK 418A, FERNVALE LINK, #06-136
SINGAPORE 791418

TP AXA
Veron.

ACCIDENT DATE : 25/08/2021

MODEL : HONDA MOBILIO SV 1.5 CVT

CHASSIS NO : MRHDD4870FP000061

ESTIMATE COST OF REPAIR BILL TO HONDA CAR NO : SGW8668S

1 PC REAR BOOTLID	<i>Distorted</i>	S\$963.90	✓
1PC MOBILIO LOGO		35.80	✓
1 PC RS LOGO	<i>new</i>	30.40	✓
1 PC I-VTEC LOGO		20.90	✓
1 PC REAR BOOTLID LOCK	<i>Damaged</i>	371.30	289
2 PC REAR BOOTLID ASBORBER	<i>Not new</i>	385.60	X
1 PC REAR BOOTLID INNER TRIMBOARD	<i>cracked</i>	268.60	✓
1 PC REAR BOOTLID RUBBER	<i>ut</i>	98.30	✓
2 PC REAR BOOTLID REFLECTOR LAMP	<i>ut</i>	381.40	✓
4 PC REAR BOOTLID REFLECTOR LAMP CLIPS	<i>New</i>	19.20	✓
1 PC REAR BOOTLID OUTER HANDLE GARNISH	<i>Not new</i>	278.70	X
1 PC REAR BOOTLID OUTER HANDLE GARNISH "H" LOGO	<i>Not new</i>	37.40	X
1 PC REAR WINDSCREEN MOULDING		118.30	✓
1 PC REAR WINDSCREEN INNER SEAL	<i>New</i>	26.00 S/NETT	✓
1 PC REAR WINDSCREEN SEALANT		45.00 S/NETT	✓
2 PC REAR TAILLAMP	<i>LH cracked, RH ut</i>	611.40	✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL : 96273323 FAX 68442641

CO.REG NO: 53049097-L

ESTIMATE COST OF REPAIR BILL TO HONDA CAR NO : SGW8668S

2 PC REAR TAILLAMP CLIPS <i>Net</i>	SS\$18.00 ✓
1 PC REAR BUMPER <i>Deformed</i>	536.80 ✓
8 PC REAR BUMPER CLIPS <i>Net</i>	30.40 ✓
2 PC REAR BUMPER SIDE RETAINER <i>Net</i>	113.60 <i>12</i> ✓
1 PC REAR BUMPER CENTRE GARNISH <i>Deformed</i>	210.70 ✓
1 PC REAR BUMPER CENTRE CHROME MOULDING <i>cracked</i>	186.50 ✓
2 PC REAR BUMPER REFLECTOR <i>cracked</i>	78.40 ✓
2 PC REAR BUMPER SPONGE <i>cracked</i>	90.80 ✓
1 PC REAR END PANEL <i>Dented</i>	424.70 ✓
1 PC REAR END PANEL GARNISH <i>cracked</i>	90.80 ✓
1 SET REAR REVERSE SENSOR <i>Damaged</i>	200.00 S/NETT ✓
1 PC REAR REVERSE CAMERA <i>Net Net</i>	680.60 X
<u>LABOUR CHARGE</u>	
WIRING	50.00 <i>30</i>
TO SPRAY PAINTING (PEARL WHITE)	1,200.00 <i>1000</i>
TO REMOVE AND REFIX REAR WINDSCREEN	150.00 <i>120</i>
TO REMOVE AND REFIX REAR INTERIOR UPHOLSTERY	80.00 ✓
TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION	80.00 ✓
TO MEASURE, DRILL THE REPLACED REAR BUMPER, POSITION & REINSTALL REVERSE SENSOR, CONTROL UNIT, CAMERA ASSY & TEST FOR FUNCTIONING	80.00 ✓
LABOUR CHARGE FOR PANEL BEATING & WELDING, REMOVING ALL DAMAGE PARTS AND REPLACING OF THE NEW PARTS ETC.	950.00 <i>800</i>

TOTAL : SS\$8,753.40

8943.50

4.9K

*total 6122.04
w/s 4.9K
07 days*