

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVE 4
#03-21 S415875

STK AUTO(S) PTE LTD

Email: stkautosg@gmail.com

Contact Person: TAN GUOHUA

HP: 91237949 / 63860669

Date: 30.08.2021

To: AXA INSURANCE PTE LTD

Attn: Motor Claim Department

ESTIMATED REPAIR COST DETAILS

Owner: KHOW CHONG LAM
Vehicle Number: SMX7778M
Make & Model: AUDI A5
Accident Date: 27.08.2021

C/N	LIST ITEM	QTY	AMOUNT S\$
1	REAR FENDER RH <i>Paint</i>	1	3358 +
2	REAR BUMPER <i>Del d</i>	1	2155 ✓
3	REAR BUMPER BRACKETS RH <i>new</i>	1	42 ✓
4	REAR SENSOR RH <i>Paint</i>	1	165 ✓
5	REAR TAIL LIGHT RH <i>cut</i>	1	1050 ✓
	<i>Rear Bumper Lower Spoiler cut</i>	1	6770 ✓
			368 ✓
			Less 5% Disc
			338.5
			Total
			6431.5

NETT ITEMS

1	REAR BUMPER CLIPS (1SET) <i>new</i>	1	50 ✓
			50
			Total
			50

LABOUR COST

1	To remove, cut out damage parts, align, panel beating and renew replace parts.	1200	600
2	To putty and respray painting on affected areas.	1240	800
3	To rewire rear portion		50
4	To remove, fix reverse sensor		150
5	To tuff kote affected areas.		80
			50
			Total
			2230

Grand Total 8711.5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
w/s 31/08/21
05 Days.
total: 4692
w/s: 3.7k.