

REF: AGZ/ 210107
REF: GRB/ 210107
& B MOTOR REPAIRS SERVICES PTE LTD
10 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722
Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640
E-Mail : tbmotor@hotmail.sg
Buss. Reg. No. : 199001597D

Page 1 / 3

WITHOUT PREJUDICE

LEONG VUN FAH
BLK322B ANCHORVALE DRIVE #11-138
SINGAPORE 542322

Attention : Motor Claim Department

Estimate : ES003436

Date : 26/08/2021
Vehicle Num. : SKW5182Z
Make/Model : HYUNDAI ELANTRA
Chassis/Eng# :
Accident Date : 26/08/2021
Claim No. :
Reference :
Policy No. : 5121185078

Not Authorised
1/18/21 @ 8750h
Accident After Rain
12 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|---------------------------------------|------------|------------|
| 1. | 1 | REAR WINDSCREEN GLASS | | |
| 2. | 1 | REAR WINDSCREEN GLASS MOULDING | | |
| 3. | 1 | REAR FENDER LH | 1658.80 | |
| 4. | 1 | REAR FENDER INNER GARNISH LH | | |
| 5. | 1 | REAR LAMP L/H | | |
| 6. | 1 | REAR LAMP INNER PANEL L/H | | |
| 7. | 1 | REAR BOOT COVER | 1832.20 | |
| 8. | 1 | REAR BOOT COVER HINGE L/H | | |
| 9. | 1 | REAR BOOT COVER HINGE R/H | | |
| 10. | 1 | REAR BOOT COVER INNER LOCK | | |
| 11. | 1 | REAR BOOT COVER REFLECTOR LH | | |
| 12. | 1 | REAR BOOT COVER REFLECTOR RH | | |
| 13. | 1 | REAR BOOT COVER LOGO | | |
| 14. | 1 | REAR BOOT COVER NUMBER PLATE LAMP R/H | | |
| 15. | 1 | REAR BOOT COVER NUMBER PLATE LAMP L/H | | |
| 16. | 1 | REAR BOOT WEATHERSTRIP | | |
| 17. | 1 | REAR END PANEL | | |
| 18. | 1 | REAR END PANEL INNER GARNISH | | |
| 19. | 1 | REAR BOOT COVER LOWER CATCH | | |
| 20. | 1 | REAR BUMPER REINFORCEMENT | | |
| 21. | 1 | REAR BUMPER REINFORCEMENT BRACKET RH | | |
| 22. | 1 | REAR BUMPER REINFORCEMENT BRACKET LH | | |
| 23. | 1 | REAR BOOT COVER ELANTRA EMBLEM | | |
| 24. | 1 | REAR BOOT COVER ELITE EMBLEM | | |
| 25. | 1 | REAR BUMPER CENTER LOWER BRACKET (A) | | |
| 26. | 1 | REAR BUMPER CENTER LOWER BRACKET (B) | | |
| 27. | 1 | REAR BUMPER | | |
| 28. | 1 | REAR BUMPER SIDE RETAINER RH | | |
| 29. | 1 | REAR BUMPER SIDE RETAINER LH | | |

Cup	463.00	✓
Re	42.00	✓
Re	1,856.00	✓
CM	48.00	✓
CM	388.00	✓
Re	171.00	✓
Re	1,840.00	✓
Re	139.00	✓
Re	139.00	✓
Re	135.00	✓
CM	298.00	✓
Re	298.00	✓
Re	28.00	✓
CM	18.00	✓
Re	18.00	✓
Re	79.00	✓
Re	454.00	✓
CM	53.00	✓
Re	17.00	✓
Re	303.00	✓
Re	40.00	✓
Re	40.00	✓
Re	48.00	✓
Re	28.00	✓
Re	15.00	✓
Re	15.00	✓
Re	459.00	✓
Re	25.00	✓
CM	25.00	✓

CONTINUE / ...

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REF: AGZ/ 210.
 REF: 1010
T & B MOTOR REPAIRS SERVICES PTE LTD
 10 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722
 Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640
 E-Mail : tbmotor@hotmail.sg
 Buss. Reg. No. : 199001597D

Page 2 / 3

WITHOUT PREJUDICE

LEONG VUN FAH
 BLK322B ANCHORVALE DRIVE #11-138
 SINGAPORE 542322

Attention : Motor Claim Department

Estimate : ES003436

Date : 26/08/2021
 Vehicle Num. : SKW5182Z
 Make/Model : HYUNDAI ELANTRA
 Chassis/Eng# :
 Accident Date : 26/08/2021
 Claim No. :
 Reference :
 Policy No. : 5121185078

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

30.	1	REAR BUMPER LOWER SPOILER
31.	1	REAR BUMPER SIDE REFLECTOR L/H
32.	1	REAR BUMPER SIDE REFLECTOR R/H
33.	1 (L/H)	REAR BUMPER SIDE LOWER COVER
34.	1 (R/H)	REAR BUMPER SIDE LOWER COVER
35.	1	REAR FLOOR BOARD COVER
36.	1	REAR BUMPER SIDE INNER TOP BRACKET R/H
37.	1	REAR BUMPER SIDE INNER TOP BRACKET L/H
38.	1	REAR FENDER LOWER INNER AIR BLOWER GARNISH LH
39.	1	REAR BUMPER MUDFLAP LH
40.	1	REAR BUMPER MUDFLAP RH
41.	8	REAR BUMPER CLIPS
42.	12	REAR BOOT GARNISH CLIPS
43.	12	REAR BOOT COVER INNER GARNISH CLIP
44.	1 SET	REAR BUMPER REVERSE SENSOR
45.	1	REAR BOOT COVER REVERSE CAMERA

List Total S\$:

20.00% Discount S\$:

Di's 251.00 ✓
 cm 28.00 ✓
 pu 28.00 x
 su 38.00 x
 su 38.00 x
 Return 220.00 ✓
 cm 15.00 ✓
 su 15.00 ✓
 Di's 59.00 ✓
 su 18.00 ✓
 su 18.00 x
 3.50 28.00 ✓
 3.50 42.00 ✓
 3.50 42.00 ✓
 cm 280.00 2 col ✓
 shot 185.00 ✓
 8,787.00
 1,757.40
 7,029.60

LABOUR :

1. TOWING
 2. TO DISMANTLE REAR WINDSCREEN & FIX
 3. TO REMOVE REAR WHEEL HOUSING AND REAR SEAT
 AND CARPET
 4. CHECK & REPAIR REAR WIRING AND FIX
 5. SPRAY PAINT ANTI-RUST COATING ON ACCIDENT PORTIONS
 6. REMOVE & REPLACE REAR BUMPER REVERSE SENSOR
 7. REMOVE & REPLACE REAR BOOT CAMERA AND WIRING & FIX

65.00 5ol
 180.00 12ol
 550.00 15ol
 180.00 2ol
 180.00 9ol
 280.00 6ol
 180.00 6ol

CONTINUE / ...

REF: AGZ/ 210.

T & B MOTOR REPAIRS SERVICES PTE LTD
SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722
No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640
Mail : tbmotor@hotmail.sg
Bus. Reg. No. : 199001597D

WITHOUT PREJUDICE

LEONG VUN FAH
BLK322B ANCHORVALE DRIVE #11-138
SINGAPORE 542322

Supplementary Estimate : ES003439

Attention : Motor Claim Department

Date : 26/08/2021
Vehicle Num. : SKW5182Z
Make/Model : HYUNDAI ELANTRA
Chassis/Eng# :
Accident Date : 26/08/2021
Claim No. :
Reference :
Policy No. : 5121185078


S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR NUMBER PLATE (EMBOSSSED)		Del 40.00
2.	1	REAR LAMP CLIPS		REC 9.00
3.	1	REAR NUMBER PLATE LAMP R/H		CM 38.00
4.	1	REAR BUMPER LOWER BRACKET		CAS 28.00
5.	1	REAR BOOT LOCK		234.00
6.	1	REAR THIRD BRAKE LIGHT		CNT 398.00
List Total S\$:				747.00
20.00% Discount S\$:				149.40
				597.60

replaced

SingDollars : Five Hundred Ninety-Seven & Cents Sixty Only

E. & O.E. Total S\$: 597.60
=====


T & B MOTOR REPAIRS SERVICES PTE LTD

OK 20/9/21

REF: AGZ/ 2100
T & B MOTOR REPAIRS SERVICES PTE LTD

Page 3 / 3

SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722
Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640
E-Mail : tbmotor@hotmail.sg
Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

LEONG VUN FAH
BLK322B ANCHORVALE DRIVE #11-138
SINGAPORE 542322

Attention : Motor Claim Department

Estimate : ES003436

Date : 26/08/2021
Vehicle Num. : SKW5182Z
Make/Model : HYUNDAI ELANTRA
Chassis/Eng# :
Accident Date : 26/08/2021
Claim No. :
Reference :
Policy No. : 5121185078

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|--|--|---|--|------------------|
| | | 8. SPRAY REAR FLOOR BOARD PANEL, REAR END PANEL, REAR FENDER LEFT, REAR FENDER RIGHT, REAR BOOT LIT, REAR BUMPER & REAR LOWER SKIRT | | 1500
2,700.00 |
| | | 9. LABOUR TO REMOVE LEFT FENDER, REAR LEFT LAMP PANEL & RIGHT LAMP PANE, END PANEL & PULL AND STRAIGHTEN AND ADJUST | | 1800
2,000.00 |
| | | 10. COMPUTER WHEEL ALIGNMENT | | nn 150.00 |
| | | 11. REMOVE & FIX REAR UNDERCARRIAGE AND ABSORBER | | nn 550.00 |
| | | 12. REMOVE & REFIX OF FUEL TANK | | 350.00 |

Labour Total S\$:

601
7,365.00

SingDollars : Fourteen Thousand Three Hundred Ninety-Four & Cents Sixty Only

19665.80

E. & O.E.

Total S\$: 14,394.60


for T & B MOTOR REPAIRS SERVICES PTE LTD